

To: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>
 Cc: ellis@adt.com.tw,
 vivi@adt.com.tw
 Subject: =?big5?B?
 pl6rSKFHIFJldmldyBvZiBBc2tleSBDb21wdXRlciBDb3JwLiwgRkNDIEIEOiA=?=
 =?us-ascii?Q?H9NWLL030M?= Permissive Change

Tim,

Did we answer your attached question ?

for (2), I confirm that the ferrite will be fixed by shrink wrap. And it
 will be done
 by the module manufacturer.

Did you get the answer for your question (1) ??

Best Regards,

Dr. Alan Lane
 Tel: +886 3 3270910
 Fax: +886 3 3270892

"Timothy R.
 Johnson" |~¥óαH¡G ellis@adt.com.tw,
 vivi@adt.com.tw
 <tjohnson@Americ °Æ¥»§Û°e¡G
 Alan_Lane@mail.adt.com.tw
 anTCB.com> ¥D!®¡G Review of Askey Computer Corp., FCC ID:
 H9NWLL030M Permissive
 Change
 2003/01/08 05:51
 AM

Ellis/Vivi,

Attached are comments regarding review of this application. Please provide
 information as soon as possible.

Thank You,

Timothy R. Johnson
NARTE Certified EMC Engineer
No. EMC-002205-NE

email: tjohnson@AmericanTCB.com
alternate email: TRJ@adelphia.net
(See attached file: ATCB Comments_010703.pdf)



[=big5BQVRDQiBDb21tZW50c18wMTA3MDMucGRm=1.pdf](#)