



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 16, 2002

RE: ASKEY COMPUTER CORP.

FCC ID: H8NWLL030M (Permissive Change)

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) There appears to be a whole section on the card that was not populated, while the original and other permissive changes show this portion of the card as populated. This information was not listed in the permissive change explanation. Please explain and if necessary adjust the operational description.
- 2) The ferrites on the antenna cables were positioned near the transmitter end of the cable. Please provide information on how the applicant insures that the OEM manufacturer will properly position the ferrites on the antenna cables given that they do not appear to be fastened. For instance, are the ferrites installed with shrink wrap or are there specific installation instructions provided to the OEM manufacturer?

Timothy R. Johnson
Examining Engineer

Direct Phone: 404-414-8071

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.