



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

May 21, 2004

RE: Askey Computer Corp.

FCC ID: H8NWLL3041

After a review of the submitted information, I have a few comments on the above referenced Application.

**Technical:**

- 1) It appears that the dipole antenna was tested upright, but the test configuration photographs appear to show the PCB antenna lying down. The report mentions that only the worse case results have been reported. Note that the FCC requires the antenna to be positioned off of the wood and arranged in a typical position. It does not appear this was done. Please review/comment/correct as necessary. Note that a retest of the PCB antenna may be necessary if not positioned correctly.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.