

Description of Permissive Change

This report is prepared for FCC class II permissive change. The differences compared with the Report No.: RF940816H02D (Part 15.247) & RF940816H0D-1 (Part 15.407) are as the following:

1. Substitution of Diplexer part: NTK LDG0UQD-3092A with Soshin HMD881J. Applicant has submitted a parts comparison analysis and believe they are electrical identical and hence only worst case antenna from previous certified list was selected for the radiated emission test.
2. Remove the DFS band<5250~5350MHz> & FCC Part 15E 5.7G band<5.745 ~ 5.805GHz>
3. Change the arrester
4. Change POE