

Symbol Technologies, Inc.

Address: One Symbol Plaza, Holtsville, NY 11742-1300

Date: April 9, 2009

Attestation

We, Symbol Technologies, Inc., hereby declare that FR6876 (model name), FCC ID: H9PFR6876 can not be used for simultaneous operation of WLAN and WWAN transmitters by software control. The software of the device will prohibit the co-transmission of both WLAN and WWAN. When WWAN mode turning on, the software of this device will shut down the transmitting of WLAN immediately. On the contrary, as the device is in the WLAN mode and users would like to use WLAN function, the software will block the WWAN usage.

Should you have any questions, please have my best attention.

Sincerely yours,



Contact Person: Andrew Ho

Company: Symbol Technologies, Inc.

Tel: + 65-6796 9635

E-mail: andrew.ho@motorola.com