



1-Mar-02

Re: Permissive Change for FCC ID H9PLA4137

Subject: Response to Correspondence Reference Number: 22135
(731 Confirmation Number EA953106)

A Class II permissive change was filed for a pending application. The change requested requires a new FCC identifier. If the two versions will both be marketed, they need separate FCC identifiers. Indicate whether both will be marketed or not. Review will continue once this is clarified.

Joe,

The Symbol radio LA-4137-1000-WW is a Compact Flash format of a 2.4 GHz DSSS radio. I included a set of photographs that shows that the LA-4137-1000-WW radio is mounted to a PCB to accommodate a PCMCIA format for the same radio.

Sec. 2.1043 Changes in certificated equipment.

(2) A Class II permissive change includes those modifications which degrade the performance characteristics as reported to the Commission at the time of the initial certification. Such degraded performance must still meet the minimum requirements of the applicable rules. When a Class II permissive change is made by the grantee, the grantee shall supply the Commission with complete information and the results of tests of the characteristics affected by such change. The modified equipment shall not be marketed under the existing grant of certification prior to acknowledgement by the Commission that the change is acceptable.

There are **no** changes or modifications to the original radio. I have included an additional set of photographs to clarify my assertions.

Regards,
Mark