

Symbol Technologies, Inc.

July 10, 2002

Andy Leimer FCC Lab, Colombia MD

Re: FCC ID: H9PLA4137

Subject: Response to the request for information

Correspondence Reference number: 23315 731 Confirmation Number: EA665115

Andy,

In response to the three items on your request for additional information:

1) A signed letter requesting that the FCC ID be changed and an explanation (error).

The signed letter has been uploaded under the title "Response to Correspondence 23315"

2) New FCC ID label. This device is using a module so the label photos should show the location on the module located inside the device and on the outside of the device.

New Label photographs and drawings have been uploaded under the title "Label, External and Internal".

3) Submit photos of the antennas.

Photographs of the antenna have been uploaded under the title "Antenna Photographs".

Regards,

Mark S. Luksich

Sr. Manager Regulatory