

Re:

Applicant: Symbol Technologies Inc

FCC ID: H9PMC7095

Correspondence Reference Number: 32884

731 Confirmation Number: EA136691

Date of Original E-Mail: 4/13/2007

Subject: Quick Review

Dear Richard,

Please see our response below, thanks.

1. In your class 2 permissive change document, it was mentioned that only the software on the device has been changed to support added spectrum. What is the mechanism that the device deploys to prevent the user from modifying the previous revision of the product and turn it into the new one?

<SYMBOL COMMENT>

The software would only be made available once the permissive change is complete, adding the band to the Grant, thus ensuring continuing compliance.

This convoluted path was a result of no FCC approved access points, that are a required part of the DFS test procedure for the 5.25 – 5.35 and 5.47 – 5.725 GHz bands, as such the bands were not able to be approved during the initial filing and is being added by this C2PC. There are no hardware changes required to enable these bands.

2. There was no new user manual uploaded. Was nothing in the document from the original filing changed?

<SYMBOL COMMENT>

There has been no change to the user guide

Best regards

Marco Belli

Marco.Belli@motorola.com

Symbol Technologies, Inc.