



June 8, 2007

Regulatory Engineering

Federal Communications Commission
Authorization and Evaluation Division

Subject: Class II Permissive Changes to remove the 5.25 – 5.35 GHz band listed on the Grant as DFS Compliance is not possible.

FCC ID: H9PWSAP5100

To the Commission:

The only change made to the following transmitters operating under FCC ID's H9PWSAP5100 with Symbol Model H9PWSAP5100 was a code update to disable the 5.25 – 5.35 GHz band. No hardware changes or modifications have been made to these transmitters. The current chipset in these transmitters does not support DFS.

I would like to also confirm that the devices listed above are commercial products that are installed, configured, and maintained by Symbol's installation group, professional installers or 3rd party professional maintenance companies. The product configuration code is password protected to prevent unauthorized access.

Respectfully,

A handwritten signature in cursive script that reads "Mark S. Luksich".

Mark S. Luksich
Director, Regulatory Engineering
631-738-5134
luksichm@symbol.com