

Model/Modèle 41A5232-1
Sears Roebuck & Co.
U.S.A.

FCC ID: **HBW1337**

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. It may, if not properly used, cause interference with other radio communications. (1) This device may not cause harmful interference. (2) This device must accept any interference received, including interference that may cause undesired operation.

Sears Canada, Inc.
Toronto, Ontario
M5B 2B8

CANADA: **RSVD**

PAT.#RE29,525; 4,037,201;
4,750,118; 4,806,830

Assembled in Mexico

132B2154-4

132LA2154-40-A
ECN:
Shown at 100%