

Lucy Tsai

From: Bartlomiej.Mucha@us.ul.com
Sent: 2011年8月2日星期二 上午 8:59
To: Lucy Tsai
Cc: Hank.Sieradzki@chamberlaingroup.com
Subject: RE: Fw: Chamberlain Group Inc, //HBW7471 //AN11T0555

Lucy,

Answers are embedded.

----- Forwarded by Hank Sieradzki/Elmhurst/CGI on 08/02/2011 07:48 AM -----

<lucy.tsai@ccsemc.com>
08/01/2011 11:28 PM

To <hank.sieradzki@chamberlain.com>
cc <lucy.tsai@ccsemc.com>
Subject Chamberlain Group Inc, //HBW7471 //AN11T0555

Hi, Mr. Hank Sieradzki,

Please address following issues.

Q#1: Please update the EUT external photos to include all sides of the EUT per 2.1033.

Ans: See attached file.

Q#2: According to the user manual, it looks like an external antenna is supplied but looks to the EUT photos, including both external and internal photos, it was not found. Please address.

Ans: Please look at the external photos - there is no external antenna. What you see in the manual is example of how to program the receiver to work with the transmitter.

Q#3: There has no information mentioned where this transmitter will be used to and its function. Please provide more information about the EUT function and usage.

Ans.: The transmitter is used with specific set of receivers mentioned in the user manual. The receivers have NO (normally open) and/or NC (normally closed) relay outputs that can be used to various applications from garage door operators, turning lights on and off, controlling entry gates and so on. Too many to list.

Best Regards,
Lucy Tsai/UL CCS

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should