

Unit External Photos

***hd33*TM 150-450**

Dual-Band Medium Power Remote Unit

FCCID: HCOHD332PSDH10A

Date: Jan 22, 2018



Dali Wireless, Inc.
535 Middlefield Road, Suite 280
Menlo Park, CA 94025
<http://www.daliwireless.com>

CONFIDENTIAL AND PROPRIETARY

This document contains information proprietary to Dali Wireless. Any disclosure, use or duplication of this document or of any of the information contained herein for other than the specific purpose for which it was disclosed is expressly prohibited, except as Dali Wireless may otherwise agree to in writing.

© Copyright 2016 Dali Wireless. All Rights Reserved

Remote Unit External Photos



Figure 1: hd33 Front view




Figure 2: hd33 Back view



Figure 3: hd33 Side view



Figure 4: hd33 Side view



Figure 5: hd33 Connector panel view



Figure 6: hd33 Top view

Model: **hd33™** -1-PS-H-10-1N-D0-002
 +48V \approx , 4.1A, 195W
 Serial Number: 10911103RA1B7B002
 MAC Address: 98:5D:AD:6C:46:67
 IPV6: fe80::9a5d:adff:fe6c:4667
 FCC ID: HCOHD332PSDH10A







LISTED
E357598 ITE

Dali Wireless, Inc. Made in Canada
 U.S. Patent www.daliwireless.com/patents

CAUTION/LASER DECLARATION



LASER RADIATION WHEN DISCONNECTED, DO NOT VIEW DIRECTLY.


Complies with 21 CFR 1040.10 and 1040.11 except for deviations pursuant to Laser Notice No. 50, dated June 24, 2007

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
 (1) this device may not cause harmful interference, and
 (2) this device must accept any interference received, including interference that may cause undesired operation

Part 90 Signal Booster
 THIS IS A 90.219 CLASS B DEVICE

WARNING. This is NOT a CONSUMER device. It is designed for Installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST Register Class B Signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

Figure 7: hd33 Labels view



UL DL UL DL

150PS 150PS 450PS 450PS

Figure 8: hd33 Labels view