

Subject: =?big5?B?pl6rSKFHIEZ3ZDogVXBkYXRlIHVIFJldmldyBvZiBBY2N0b24=?= Technology Corporation, FCC ID: HED3CRWE554G72  
To: tjohnson@AmericanTCB.com

Dear Timothy,  
For the case,  
item 1) - we upload the revised internal photo.  
item 2) - we upload the revised manual and revised report-2  
Thanks!  
Best Regards,  
Amanda Chu

~~~~~  
Certification Specialist  
ADT Corp. (Hsin Chu Office)  
TEL: 03-5935343 ext. 1737  
FAX: 03-5935342  
~~~~~

Dear Timothy,  
For the case,  
item 1) - we will provide to you asap.  
item 2) - the correct cable is unshielded cable. The UTP cable which was described in th report is Unshielded Twist Pair Cable, if we showed "STP cable", that's mean Shielded Twist Pair. As no any informaion explains the cable type in the report, so caused the misunderstand. The revised manual will send to you asap.  
Sorry for the delay, If you have any further comments or questions, please do not hesitate to contact with me or Amanda, thanks a lot.  
Regards,

^LçãÛy / Eric Lin