



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

May 17, 2002

RE: Accton Technology Corporation

FCC ID: HEDM506BWN3101A-1

I have a few comments on this Application.

- 1.) Please provide a block diagram with more detail as required by 47CFR 2.1033(b)(5)
- 2.) Please provide a revised label with the FCC ID: on the same line as Grantee code and product code.
- 3.) The Manual appears to indicate that this device also contains a modem capable of connecting to a phone line. Is this true? I do not see any PSTN interface on this card. If so, please provide a copy of the suppliers Declaration of Conformity on this device.
- 4.) There does not appear any prohibition for modifications as required in 47CFR 15.21.

William H. Graff  
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.