

Mike Kuo

From: ting@ccsemc.com.tw on behalf of application@ccsemc.com.tw
Sent: October 19日 2004年 Tuesday 7:01 PM
To: Mike Kuo
Cc: CCS- Application (E-mail)
Subject: 回信 : FW: Accton Technology Corporation, FCC ID: HEDWA6102X, Assessment NO.: AN04T4253, Notice#1



WA6102X UserMan revised 1020.p...
WA6102X TestRpt DTS revised 10...

Hi Mike,

Please refer to the following for our replies. Thank you for your advice.

Best regards,
Ting

Mike Kuo
<MKUO@CCSEMC.com> 收件人 : "CCS- Application (E-mail)" <application@ccsemc.com.tw>
副本抄送 :
2004/10/19 03:45 PM 主旨 : FW: Accton Technology Corporation, FCC ID: HEDWA6102X, Assessment NO.: AN04T4253, Notice#1

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]
Sent: Tuesday, October 19, 2004 12:23 AM
To: Mike Kuo
Subject: Accton Technology Corporation, FCC ID: HEDWA6102X, Assessment NO.: AN04T4253, Notice#1

Question #1: Page 120 and 121 of EMC test report with radiated spurious emission data failed 15.209 average limits. Please address these non-compliance issue.

Ans #1: This is typo and the test report is corrected. Please refer to the attached.

Question #2: section 5-5, 5-43 and 5-48 of user manual mentioned about the system country code and channel selection . To inform the user about the regulatory requirements but without the hardware limitation to limit selection is not acceptable. Please provide technical description on how the manufacturer will limit the end user to operate within authorized U.S. channel.

Ans #2: The channel will be disable by software, please refer to the attached revised user manual, page 83.

(See attached file: WA6102X UserMan revised 1020.pdf)(See attached file: WA6102X TestRpt DTS revised 1019.pdf)

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.