


## Appendix C. Set up Photograph **Conducted Emission**



FRONT VIEW



SPORTON International Inc. TEL: 886-2-2696-2468 FAX : 886-2-2696-2255

Page No. : C1 of C5 Report Issued Date : Oct. 17, 2005 FCC ID : HFS-Atom Report Version

: Rev. 01






SIDE VIEW

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 Page No.: C2 of C5Report Issued Date: Oct. 17, 2005FCC ID: HFS-AtomReport Version: Rev. 01





## **Conducted Emission**



FRONT VIEW

**REAR VIEW** 

SPORTON International Inc. TEL: 886-2-2696-2468 FAX : 886-2-2696-2255

Page No. : C3 of C5 Report Issued Date : Oct. 17, 2005 : HFS-Atom FCC ID Report Version : Rev. 01






SIDE VIEW

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 Page No.: C4 of C5Report Issued Date: Oct. 17, 2005FCC ID: HFS-AtomReport Version: Rev. 01



## **Radiation Emission**



FRONT VIEW

**REAR VIEW** 

SPORTON International Inc. TEL: 886-2-2696-2468 FAX : 886-2-2696-2255

: C5 of C5 Page No. Report Issued Date : Oct. 17, 2005 : HFS-Atom FCC ID Report Version : Rev. 01