

Hi Jim,

We have completed our review and have identified the following issues:

1. The form 731 quoted the grantee code to be HUR, however we believe it should be HJR. HUR is also used throughout the application. There is no need to correct the all the documentation as I will add an exhibit to the FCC filing to correct the error. However I would like a corrected tested report. The label has the correct code.

Response – Revised test report supplied.

2. Please include in the manual information to the user and installer procedures to implement the requirements of 15.242 (d) and 15.242 (e). We do not currently find any information in the user's manual informing the user about their responsibilities with regard to coordination of use with existing TV stations and radio astronomy observatories.

Response – Revised manual supplied.

3. Please confirm that device was tested in three orthogonal planes to maximize emissions.

Response – Revised test report supplied.

4. Please include instructions in the manual that this device is for use solely on the premises of health care facilities. See 15.242 (a).

Response – Revised manual supplied.

Best regards

Barry C. Quinlan
Certification & Telecom Manager

Curtis-Straus LLC Voice: 978.486.8880 x270
527 Great Road Fax: 978.486.8828
Littleton, MA 01460 <http://www.curtis-straus.com>
