



**Acer Incorporated**  
8F, 88, Sec. 1, Hsin Tai Wu Rd., Hsichih  
Taipei Hsien 221, Taiwan, R.O.C.  
Tel : 886-2-2696-1234 Fax : 886-2-2696-3535  
[www.acer.com](http://www.acer.com)

**Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046**

**Attention: Application Examiner/ Review Engineer**

**Subject: Request to change in identification per section 2.933 of FCC rules**

**Reference: FCC ID: HLZ- BRCM1053**

**To The Commission:**

**This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Acer Incorporated will establish a new FCC ID under Acer Incorporated grantee code for purpose of marketing. The original grant to FCC ID: QDS- BRCM1053. will remain in effect.**

**Per 2.933(b)**

**The original identification is FCC ID: QDS-BRCM1053**

- 1. The original grant date is 11/10/2010**
- 2. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.**
- 3. The original test results are applicable and representative of this changed device.**
- 4. Exterior photographs are included in this application.**

**The following files are electronically submitted as attachments:**

**Cover Letter  
External Photos  
FCC ID label format and location**

**Sincerely,**

---

**Acer Incorporated  
Ru Jan / Manager  
Date:2011/03/30**