

⊙ +/-0.2

15 MM

acer

Model No.: W511
FCC ID: HLZW510
IC: 1754F-W510
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZMU733

Contains IC: 1754F-MU733

Contains FCC ID: HLZ-T77H389

Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

⊙ +/-0.2

15 MM

acer
Model No.: W511P
FCC ID: HLZW510
IC: 1754F-W510
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZMU733
Contains IC: 1754F-MU733
Contains FCC ID: HLZ-T77H389
Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

⊙ +/-0.2

15 MM

acer
Model No.: WT3
FCC ID: HLZW510
IC: 1754F-W510
CNC: C-10XXX



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy

Contains FCC ID: HLZMU733
Contains IC: 1754F-MU733
Contains FCC ID: HLZ-T77H389
Contains IC: 1754F-T77H389



Acer Italy s.r.l./Via Lepetit, 40, 20020 Lainate (MI) Italy