

Reference No.:A03110506 Report No.:FCCA03110506 FCC ID: HQXAXM-105678

Page:1 of 6

Date:Nov. 21, 2003

PHOTOS OF TESTING

- Conducted test (Mode 1)







Lab Code: 200099-0



Reference No.:A03110506 Report No.:FCCA03110506 FCC ID: HQXAXM-105678


Page:2 of 6

Date:Nov. 21, 2003

- Conducted test (Mode 2)








Reference No.:A03110506 Report No.:FCCA03110506 FCC ID: HQXAXM-105678

Page:3 of 6

Date:Nov. 21, 2003

- Conducted test (Mode 3)







Reference No.:A03110506 Report No.:FCCA03110506 FCC ID: HQXAXM-105678


Page:4 of 6

Date:Nov. 21, 2003

- Radiated test (Mode 1)







Reference No.:A03110506 Report No.:FCCA03110506 FCC ID: HQXAXM-105678


Page:5 of 6

Date:Nov. 21, 2003

- Radiated test (Mode 2)







Reference No.:A03110506 Report No.:FCCA03110506 FCC ID: HQXAXM-105678

Page:6 of 6

Date:Nov. 21, 2003

- Radiated test (Mode 3)



