

95026

# ELECTRONICS TESTING CENTER, TAIWAN

No.8, Lane 29, Wen-Ming RD., Lo-Shan Tsun, Kui-Shan Hsiang,  
Taoyuan Hsien 333, Taiwan, R.O.C.

TEL : (03)3280026

FAX : (03)3280034

## FCC REPORT FOR REPLY TO CORRECTION

*Exhibit L*

**TO:** FCC Application Processing Branch

**ATTN:** Ms. Linda Elliott

**DATE:** August 20, 1999

**FAX NO:** 002-1-301-344 2056

(A) FCC ID: HQXPC98617-01

(B) REPORT NO: ET88S-06-096

(C) CORRESPONDENCE REFERENCE NO.: 9134

(D) 731 CONFIRMATION NUMBER: EA95026

(E) APPLICANT: SYSGRATION LTD.

(F) MODEL: Pro 1000, Pro 1400

(G) REPLY FOR E-MAIL ON August 09, 1999:

Please see attachment of correction label for replacement.

*ACILE 8/23/99*

APPROVE & AUTHORIZED SIGNER: Win-Po Tsai *Aug 20, 1999*

WIN-PO TSAI, SUPERVISOR, NVLAP SIGNATORY  
EMC DEPT. OF ELECTRONICS TESTING CENTER,  
TAIWAN

**MINUTEMAN**  
model:  
**Pro 1000**



**INPUT**

115VAC, 50/60Hz  
12A MAX

**OUTPUT**

115VAC, 50/60Hz  
5A MAX

**SURGE OUT**

115VAC, 50/60Hz  
7A MAX

FCC ID: HQXPC98617-01

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:  
(1) This device may not cause harmful interference, and  
(2) this device must accept any interference received, including interference that may cause undesired operation.

P/N : 90000309

S/N : AC51

LB-0507-37A

**MINUTEMAN**  
model:  
**Pro 1400**



**INPUT**

115VAC, 50/60Hz  
12A MAX

**OUTPUT**

115VAC, 50/60Hz  
7A MAX

**SURGE OUT**

115VAC, 50/60Hz  
5A MAX

FCC ID: HQXPC98617-01

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:  
(1) This device may not cause harmful interference, and  
(2) this device must accept any interference received, including interference that may cause undesired operation.

P/N : 90000310

S/N : AC52

LB-0507-38A