



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 6, 2003

RE: Cirronet

FCC ID: HSW-2410M

I have a few comments on the above referenced Application.

- 1) The test configuration photograph appears to show a different device vs. what was originally approved. Please explain.
- 2) It appears that the conducted data table may contain errors. Additionally, compliance should be shown from 0.15 - 30 MHz in order to place CE note per our discussion. Please verify.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.