

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

Worst Case Position


ECU
 Below 30 MHz
 X-axis
 Above 30 MHz
 Horizontal: X-axis / Vertical: X-axis
 X-axis




Y-axis




Z-axis



Rear(Front) Bumper/Frunk Antenna
 Below 30 MHz
 X-axis
 Above 30 MHz
 Horizontal: X-axis / Vertical: X-axis
 X-axis



Y-axis




Z-axis




Worst Case Position


Interior Antenna
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis
X-axis



Y-axis



Z-axis




Trunk Antenna
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis
X-axis



Y-axis



Z-axis



Worst Case Position

Immo Combo Antenna

Below 30 MHz

X-axis


Above 30 MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



Immo Combo Antenna

With key



Without key (Worst)



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124