



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 14, 2006

RE: Micro-Star Intl. Co. Ltd.

FCC ID: I4L-MS6872

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The label is of incorrect format for this device. Please use "FCC ID: I4L-MS6872". Please recheck and change your labeling to conform to FCC Rules.
- 2.) There are three dwell time modes of interest. DH1, DH3, and DH5. can you kindly provide data for each mode within the Test Reports?
- 3.) Spurious emissions – especially at the band edges – should be checked in both hopping and non-hopping mode. Was this done?

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.