

Class II permissive change request letter

Date (08/09/2018)

TUV SUD BABT

Octagon House,
Segensworth Road,
Fareham,
Hampshire,
PO15 5RL

REF: Class II permissive change for FCC ID: I6H-MMK100, IC: 21449-MMK100

Dear Sir or Madam,

Pursuant to section 2.1043, and IC RSP-100 Sec. 4.4, we Nortek Security & Control LLC. Hereby submit a request for class II permissive change for FCC ID: I6H-MMK100 Issued 2017-08-18, IC: 21449-MMK100 Issued 2017-08-18

Description of the change:

The reason for the C2PC is that a capacitor value was changed from (10) pF to (8.2) pF which caused a degradation in data on file with FCC and ISED.



Josh Hansen

Engineering Manager, Regulatory

Nortek Security & Control LLC/GTO