



October 12, 2004

TCB
TÜV America, Inc.
10040 Mesa Rim Road
San Diego, CA 92121

Re: LPT-900

Dear Sir or Madam:

From a component standpoint, the only change is the synthizer chip which was done because of the current one becoming obsolete. The PCB layout was also altered for improved performance, particularly less susceptibility to strong external electrical noise.

Sincerely,

A handwritten signature in black ink, appearing to read "Martin Steenblok". The signature is fluid and cursive, with a prominent initial "M" and a long, sweeping underline.

Martin Steenblok
Ph.: 604-944-9247
Fax: 604-944-9267