

Eaton

DBA Cooper Industries (Electrical) Inc. 74 – 1833 Coast Meridian Road Port Coquitlam BC Canada V3C6G5

TD110-2.4GHz

Internal Photos

Radu Oprea 06-IA9-D11024_Internal_Photos.docx




Figure 1 TD110-2.4 GHz PCB top view with key domes removed.




Figure 2 TD110-2.4 GHz PCB bottom with battery and RF shield installed.




Figure 3 TD110-2.4 GHz PCB bottom view.



Figure 4 TD110-2.4 GHz Back Shell Assembly.




Figure 5 TD110-2.4GHz Front Shell Assembly.