



Intertek Testing Services

ETL SEMKO

Report No.: 0310035
Cam & Receiver ON

Tested By: Hong, Report No.: 0310035


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN	OFF 60dB

Final Measurement: x QP / + AV

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No. Start Stop Name
21 9k 30M EW0698





Intertek Testing Services

ETL SEMKO

Report No.: 0310035
Cam & Receiver ON

Tested By: Hong, Report No.: 0310035

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN	OFF 60dB

Final Measurement

no Results