To: Nicholas Abbondante ES-Box Cc: Danielle Fontaine ES-Box

Subject: LoJack FCC ID: IDILJU-03U Permissive Change Application

Nick,

Review of this application is complete, and the following points are noted:

ADMINISTRATIVE

Description of changes indicates that a new enclosure is the reason for the application. Please provide external photos documenting (1) the new enclosure, and (2) any new location of the label containing the FCC Identifier, if the location has changed.

TECHNICAL

The original application reported a necessary bandwidth of $13.2~\mathrm{kHz}$. This application reports $16.8~\mathrm{kHz}$, with no changes to the RF circuitry. The necessary (or occupied) bandwidth should not be changed by a new enclosure. The difference is likely caused by the difference in resolution bandwidths from the original application (300 Hz) to this application (3 kHz) when measuring the emission. Please re-measure the occupied bandwidth using a 300 Hz RBW, and provide the new measurement, preferably as an amended report.

Certification can be completed when this information is received.

Roland