Report Number: 101083806BOX-001 Issued: 03/25/2013

## 6 Occupied Bandwidth

## 6.1 Method

Tests are performed in accordance with FCC CFR47 Part 2.1049, 90.209, and TIA-603-C.

**TEST SITE:** EMC Lab

6.2 Test Equipment Used:

Asset	Description	Manufacturer	Model	Serial	Cal Date	Cal Due
			ESCI			
			1166.5950K0			
ROS002'	9kHz to 3GHz EMI Test Receiver	Rohde & Schwartz	3	100067	06/13/2012	06/13/2013
				CBLBNC2012		
CBLBNC2012-2'	50 Ohm Coaxial Cable	Pomona	RG-58 C/U	-2	09/14/2012	09/14/2013
DAV001'	Weather Station	Davis Instruments	7400	PE80519A61	08/28/2012	08/28/2014


## **Software Utilized:**

Name	Manufacturer	Version
None		

## 6.3 Results:

The sample tested was found to Comply. The occupied bandwidth must not exceed 11.25 kHz for a 12.5 kHz authorized bandwidth.

6.4 Setup Photographs:



Non-Specific EMC Report Shell Rev. January 2013 LoJack Corporation, Model: RLU7 Report Number: 101083806BOX-001 Issued: 03/25/2013

7.4 Setup Photographs:

