





### RX-5 light M-Link mounting the assembled PCB, header and contact PCB



#### 1. soldering header --> PCB




- Header touches the PCB edge
- Attention: solder it at right angles with the PCB




#### 2. contact PCB

soldering the upper pins



soldering a pin or a piece of wire  
contact PCB --> main PCB



After the assembly the programming of the receiver has to be made.  
Please refer to test instruction No. 20056 for RX-5 light M-Link / RX-5 M-Link ID