FCC RF Test Report

APPLICANT : Motorola Mobility LLC EQUIPMENT : Mobile Cellular Phone

BRAND NAME : Motorola

MODEL NAME : XT2311-3, XT2311-4, XT2311DL

FCC ID : IHDT56AH4

STANDARD : FCC Part 15 Subpart C §15.247

CLASSIFICATION : (DSS) Spread Spectrum Transmitter

TEST DATE(S) : Oct. 08, 2022 ~ Oct. 28, 2022

We, Sporton International Inc. (Kunshan), would like to declare that the tested sample has been evaluated in accordance with the test procedures and has been in compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of Sporton International Inc. (Kunshan), the test report shall not be reproduced except in full.

JasonJia

Approved by: Jason Jia





Report No.: FR292212A

Sporton International Inc. (Kunshan)

No. 1098, Pengxi North Road, Kunshan Economic Development Zone Jiangsu Province 215300 People's Republic of China

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 1 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

TABLE OF CONTENTS

RE	VISIO	N HISTORY	3
SU	MMAR	RY OF TEST RESULT	4
1	GENE	ERAL DESCRIPTION	5
	1.1	Applicant	5
	1.2	Manufacturer	5
	1.3	Product Feature of Equipment Under Test	5
	1.4	Product Specification of Equipment Under Test	5
	1.5	Modification of EUT	6
	1.6	Specification of Accessory	6
	1.7	Testing Location	6
	1.8	Test Software	6
	1.9	Applicable Standards	7
2	TEST	CONFIGURATION OF EQUIPMENT UNDER TEST	8
	2.1	Carrier Frequency Channel	8
	2.2	Test Mode	9
	2.3	Connection Diagram of Test System	10
	2.4	Support Unit used in test configuration and system	11
	2.5	EUT Operation Test Setup	11
	2.6	Measurement Results Explanation Example	11
3	TEST	RESULT	12
	3.1	Number of Channel Measurement	12
	3.2	Hopping Channel Separation Measurement	14
	3.3	Dwell Time Measurement	20
	3.4	20dB and 99% Bandwidth Measurement	
	3.5	Output Power Measurement	33
	3.6	Conducted Band Edges Measurement	34
	3.7	Conducted Spurious Emission Measurement	41
	3.8	Radiated Band Edges and Spurious Emission Measurement	51
	3.9	AC Conducted Emission Measurement	
	3.10	Antenna Requirements	57
4	LIST	OF MEASURING EQUIPMENT	58
5	UNC	ERTAINTY OF EVALUATION	59
ΑP	PEND	IX A. CONDUCTED TEST RESULTS	
ΑP	PEND	IX B. AC CONDUCTED EMISSION TEST RESULT	
		IX C. RADIATED SPURIOUS EMISSION	
ΑP	PEND	IX D. DUTY CYCLE PLOTS	
ΔP	DENID	IY F SETUP PHOTOGRAPHS	

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 2 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No. : FR292212A

REVISION HISTORY

REPORT NO.	VERSION	DESCRIPTION	ISSUED DATE
FR292212A	Rev. 01	Initial issue of report	Nov. 10, 2022

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 3 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No. : FR292212A

SUMMARY OF TEST RESULT

Report Section	FCC Rule	Description	Limit	Result	Remark
3.1	15.247(a)(1)	Number of Channels	≥ 15Chs	Pass	-
3.2	15.247(a)(1)	Hopping Channel Separation	≥ 2/3 of 20dB BW	Pass	-
3.3	15.247(a)(1)	Dwell Time of Each Channel	≤ 0.4sec in 31.6sec period	Pass	-
3.4	15.247(a)(1)	20dB Bandwidth	1	Report only	-
3.4	-	99% Bandwidth	-	Report only	-
3.5	15.247(b)(1)	Peak Output Power	≤ 125 mW	Pass	-
3.6	15.247(d)	Conducted Band Edges	≤ 20dBc	Pass	-
3.7	15.247(d)	Conducted Spurious Emission	≤ 20dBc	Pass	-
3.8	15.247(d)	Radiated Band Edges and Radiated Spurious Emission	15.209(a) & 15.247(d)	Pass	Under limit 4.18 dB at 42.61 MHz
3.9	15.207	AC Conducted Emission	15.207(a)	Pass	Under limit 7.87 dB at 0.164 MHz
3.10	15.203 & 15.247(b)	Antenna Requirement	15.203 & 15.247(b)	Pass	-

Declaration of Conformity:

The test results with all measurement uncertainty excluded are presented in accordance with the regulation limits or requirements declared by manufacturers.

Comments and Explanations:

The declared of product specification for EUT presented in the report are provided by the manufacturer, and the manufacturer takes all the responsibilities for the accuracy of product specification.

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 4 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

1 General Description

1.1 Applicant

Motorola Mobility LLC

222 W, Merchandise Mart Plaza, Chicago IL 60654 USA

1.2 Manufacturer

Motorola Mobility LLC

222 W, Merchandise Mart Plaza, Chicago IL 60654 USA

1.3 Product Feature of Equipment Under Test

Product Feature					
Equipment	Mobile Cellular Phone				
Brand Name	Motorola				
Model Name	XT2311-3, XT2311-4, XT2311DL				
FCC ID	IHDT56AH4				
	Conducted: 358373300033767				
IMEI Code	Conduction: 358373300025292				
	Radiation: 358373300025870/358373300025801				
HW Version	DVT2				
SW Version	TTO33.44				
EUT Stage	Identical Prototype				

Report No.: FR292212A

Remark: The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.

1.4 Product Specification of Equipment Under Test

Standards-related Product Specification					
Tx/Rx Frequency Range	2402 MHz ~ 2480 MHz				
Number of Channels	79				
Carrier Frequency of Each Channel	2402+n*1 MHz; n=0~78				
Maximum Output Power to Antenna	Bluetooth BR(1Mbps) : 14.03 dBm (0.0253 W) Bluetooth EDR (2Mbps) : 12.91 dBm (0.0195 W) Bluetooth EDR (3Mbps) : 13.05 dBm (0.0202 W)				
99% Occupied Bandwidth	Bluetooth BR(1Mbps) : 0.758 MHz Bluetooth EDR (2Mbps) : 1.140 MHz Bluetooth EDR (3Mbps) : 1.123 MHz				
Antenna Type / Gain	IFA Antenna type with gain -3.1 dBi				
Type of Modulation	Bluetooth BR (1Mbps) : GFSK Bluetooth EDR (2Mbps) :π/4-DQPSK Bluetooth EDR (3Mbps) : 8-DPSK				

 Sporton International Inc. (Kunshan)
 Page Number
 : 5 of 59

 TEL: +86-512-57900158
 Report Issued Date
 : Nov. 10, 2022

 FAX: +86-512-57900958
 Report Version
 : Rev. 01

FCC ID: IHDT56AH4 Report Template No.: BU5-FR15CBT Version 2.0

1.5 Modification of EUT

No modifications are made to the EUT during all test items.

1.6 Specification of Accessory

Specification of Accessory						
AC Adapter 1	Brand Name	Motorola(AOHAI)	Model Name	MC-101		
AC Adapter 2	Brand Name	Motorola(Chenyang)	Model Name	MC-101		
AC Adapter 3	Brand Name	Motorola(Salcomp)	Model Name	MC-101		
Battery 1	Brand Name	Motorola (Sunwoda)	Model Name	PD50		
Battery 2	Brand Name	Motorola (SCUD)	Model Name	PD50		
USB Cable 1	Brand Name	HX	Model Name	S928D43190		
USB Cable 2	Brand Name	NAEE	Model Name	S928D43191		

Report No.: FR292212A

1.7 Testing Location

Sporton International Inc. (Kunshan) is accredited to ISO/IEC 17025:2017 by American Association for Laboratory Accreditation with Certificate Number 5145.02.

Test Firm	Sporton International Inc. (Kunshan)					
	No. 1098, Pengxi North	n Road, Kunshan Econom	ic Development Zone			
Toot Site Leastion	Jiangsu Province 215300 People's Republic of China					
Test Site Location	TEL: +86-512-57900158					
	FAX: +86-512-57900958					
	Sporton Site No.	FCC Designation No.	FCC Test Firm			
Test Site No.	Sporton Site No.	rcc besignation No.	Registration No.			
Test one NO.	CO01-KS 03CH06-KS TH01-KS	CN1257	314309			

1.8 Test Software

Item	Site	Manufacturer	Name	Version
1.	03CH06-KS	AUDIX	E3	6.2009-8-24al
2.	CO01-KS	AUDIX	E3	6.2009-8-24

 Sporton International Inc. (Kunshan)
 Page Number
 : 6 of 59

 TEL: +86-512-57900158
 Report Issued Date
 : Nov. 10, 2022

 FAX: +86-512-57900958
 Report Version
 : Rev. 01

FCC ID: IHDT56AH4 Report Template No.: BU5-FR15CBT Version 2.0

1.9 Applicable Standards

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- 47 CFR Part 15 Subpart C §15.247
- FCC KDB 558074 D01 15.247 Meas Guidance v05r02
- ANSI C63.10-2013

Remark:

- 1. All test items were verified and recorded according to the standards and without any deviation during the test.
- 2. This EUT has also been tested and complied with the requirements of FCC Part 15, Subpart B, recorded in a separate test report.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 7 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR292212A

2 Test Configuration of Equipment Under Test

2.1 Carrier Frequency Channel

Frequency Band	Channel	Freq. (MHz)	Channel	Freq. (MHz)	Channel	Freq. (MHz)
	0	2402	27	2429	54	2456
	1	2403	28	2430	55	2457
	2	2404	29	2431	56	2458
	3	2405	30	2432	57	2459
	4	2406	31	2433	58	2460
	5	2407	32	2434	59	2461
	6	2408	33	2435	60	2462
	7	2409	34	2436	61	2463
	8	2410	35	2437	62	2464
	9	2411	36	2438	63	2465
	10	2412	37	2439	64	2466
	11	2413	38	2440	65	2467
	12	2414	39	2441	66	2468
2400-2483.5 MHz	13	2415	40	2442	67	2469
	14	2416	41	2443	68	2470
	15	2417	42	2444	69	2471
	16	2418	43	2445	70	2472
	17	2419	44	2446	71	2473
	18	2420	45	2447	72	2474
	19	2421	46	2448	73	2475
	20	2422	47	2449	74	2476
	21	2423	48	2450	75	2477
	22	2424	49	2451	76	2478
	23	2425	50	2452	77	2479
	24	2426	51	2453	78	2480
	25	2427	52	2454	-	-
	26	2428	53	2455	-	-

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 8 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

2.2 Test Mode

a. The EUT has been associated with peripherals and configuration operated in a manner tended to maximize its emission characteristics in a typical application. Frequency range investigated: conduction emission (150 kHz to 30 MHz), radiation emission (9 kHz to the 10th harmonic of the highest fundamental frequency or to 40 GHz, whichever is lower). For radiated measurement, pre-scanned in three orthogonal panels, X, Y, Z. The worst cases (X plane) were recorded in this report, and the worst mode of radiated spurious emissions is Bluetooth 1Mbps mode, and recorded in this report.

Report No.: FR292212A

b. AC power line Conducted Emission was tested under maximum output power.

The following summary table is showing all test modes to demonstrate in compliance with the standard.

Summary table of Test Cases							
	Data Rate / Modulation						
Test Item	Bluetooth BR 1Mbps	Bluetooth EDR 2Mbps	Bluetooth EDR 3Mbps				
	GFSK	π/4-DQPSK	8-DPSK				
Conducted	Mode 1: CH00_2402 MHz	Mode 4: CH00_2402 MHz	Mode 7: CH00_2402 MHz				
	Mode 2: CH39_2441 MHz	Mode 5: CH39_2441 MHz	Mode 8: CH39_2441 MHz				
Test Cases	Mode 3: CH78_2480 MHz	Mode 6: CH78_2480 MHz	Mode 9: CH78_2480 MHz				
	Bluetooth BR 1Mbps GFSK						
		Bluetooth Bit Thisps of oit					
Radiated		Mode 1: CH00_2402 MHz					
Radiated Test Cases							
		Mode 1: CH00_2402 MHz					
	M - 1 - 00M050 - 11 - DI	Mode 1: CH00_2402 MHz Mode 2: CH39_2441 MHz Mode 3: CH78_2480 MHz					
Test Cases		Mode 1: CH00_2402 MHz Mode 2: CH39_2441 MHz Mode 3: CH78_2480 MHz uetooth Link + WLAN Link (2.4					
Test Cases	Mode 1 : GSM 850 Idle + BI from Adapter 3) + E	Mode 1: CH00_2402 MHz Mode 2: CH39_2441 MHz Mode 3: CH78_2480 MHz uetooth Link + WLAN Link (2.4					

Remark:

- 1. For radiated test cases, the worst mode data rate 1Mbps was reported only, because this data rate has the highest RF output power at preliminary tests, and no other significantly frequencies found in conducted spurious emission.
- 2. For Radiated Test Cases, The tests were performed with Adapter 2, USB Cable 2 and Earphone.
- 3. The accessories are from the worst mode of Part 15B report.

 Sporton International Inc. (Kunshan)
 Page Number
 : 9 of 59


 TEL: +86-512-57900158
 Report Issued Date
 : Nov. 10, 2022

 FAX: +86-512-57900958
 Report Version
 : Rev. 01


FCC ID: IHDT56AH4 Report Template No.: BU5-FR15CBT Version 2.0

2.3 Connection Diagram of Test System

AC Conducted Emission:



Radiated Emission:



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 10 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

2.4 Support Unit used in test configuration and system

Item	Equipment	Trade Name	Model Name	FCC ID	Data Cable	Power Cord
1.	LTE Base Station	Anritus	MT8820C	N/A	N/A	Unshielded,1.8m
2.	Bluetooth Earphone	Lenovo	LBH308	N/A	N/A	N/A
3.	Notebook	Lenovo	G480	QDS-BRCM1050I	N/A	shielded cable DC O/P 1.8m , Unshielded AC I/P cable 1.8m
4.	WLAN AP	D-link	DIR-655	KA21R655B1	N/A	Unshielded,1.8m
5.	SD Card	Kingston	8GB	N/A	N/A	N/A
6.	Earphone	Lenovo	P121	N/A	N/A	Unshielded,1.2m
7.	BT Base Station	R&S	CBT	N/A	N/A	Unshielded, 1.8m

2.5 EUT Operation Test Setup

For Bluetooth function, the engineering test program was provided and enabled to make EUT connect with Bluetooth base station to continuous transmit.

For AC power line conducted emissions, the EUT was set to connect with the WLAN AP under large package sizes transmission.

2.6 Measurement Results Explanation Example

For all conducted test items:

The offset level is set in the spectrum analyzer to compensate the RF cable loss and attenuator factor between EUT conducted output port and spectrum analyzer. With the offset compensation, the spectrum analyzer reading level is exactly the EUT RF output level.

Example:

The spectrum analyzer offset is derived from RF cable loss.

Offset = RF cable loss.

Following shows an offset computation example with cable loss 6.0dB.

 $Offset(dB) = RF \ cable \ loss(dB)$ = 6.0 (dB) Report No.: FR292212A

3 Test Result

3.1 Number of Channel Measurement

3.1.1 Limits of Number of Hopping Frequency

Frequency hopping systems in the 2400-2483.5 MHz band shall use at least 15 channels.


3.1.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.1.3 Test Procedure

- 1. The testing follows ANSI C63.10-2013 clause 7.8.3.
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Enable the EUT hopping function.
- 5. Use the following spectrum analyzer settings: Span = the frequency band of operation; RBW = 300kHz; VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold.
- 6. The number of hopping frequency used is defined as the number of total channel.
- 7. Record the measurement data derived from spectrum analyzer.

3.1.4 Test Setup



Sporton International Inc. (Kunshan) TEL: +86-512-57900158


FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 12 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.1.5 Test Result of Number of Hopping Frequency


Please refer to Appendix A.

Number of Hopping Channel Plot on Channel 00



Date: 8.OCT.2022 01:25:01

Number of Hopping Channel Plot on Channel 78



Date: 8.OCT.2022 01:25:31

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 13 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.2 Hopping Channel Separation Measurement

3.2.1 Limit of Hopping Channel Separation

Frequency hopping systems operating in the 2400-2483.5 MHz band may have hopping channel carrier frequencies that are separated by 25 kHz or two-thirds of the 20 dB bandwidth of the hopping channel, whichever is greater.


3.2.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.2.3 Test Procedures

- 1. The testing follows ANSI C63.10-2013 clause 7.8.2.
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Enable the EUT hopping function.
- 5. Use the following spectrum analyzer settings: Span = wide enough to capture the peaks of two adjacent channels; RBW = 300kHz; VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold.
- 6. Measure and record the results in the test report.

3.2.4 Test Setup



Sporton International Inc. (Kunshan) Page Number TEL: +86-512-57900158 Report Issued Date: Nov. 10, 2022 FAX: +86-512-57900958

FCC ID: IHDT56AH4

Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

: 14 of 59


Report No.: FR292212A

3.2.5 Test Result of Hopping Channel Separation

Please refer to Appendix A.


<1Mbps>

Channel Separation Plot on Channel 00 - 01



Date: 8.OCT.2022 00:59:11

Channel Separation Plot on Channel 39 - 40




Date: 8.OCT.2022 01:07:07

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 15 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


Channel Separation Plot on Channel 77 - 78



Date: 8.OCT.2022 01:18:05

<2Mbps>

Channel Separation Plot on Channel 00 - 01




Date: 8.OCT.2022 01:49:19

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 16 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

Channel Separation Plot on Channel 39 - 40



Date: 8.OCT.2022 01:56:35

Channel Separation Plot on Channel 77 - 78



Date: 8.OCT.2022 02:02:53


Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 17 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<3Mbps>

Channel Separation Plot on Channel 00 - 01



Date: 8.OCT.2022 02:10:39

Channel Separation Plot on Channel 39 - 40




Date: 8.OCT.2022 02:28:18

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 18 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

Channel Separation Plot on Channel 77 - 78



Date: 8.OCT.2022 02:37:55

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 19 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.3 Dwell Time Measurement

3.3.1 Limit of Dwell Time

The average time of occupancy on any channel shall not be greater than 0.4 seconds within a period of 0.4 seconds multiplied by the number of hopping channels employed.


3.3.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.3.3 Test Procedures

- 1. The testing follows ANSI C63.10-2013 clause 7.8.4.
- The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator.
 The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Enable the EUT hopping function.
- 5. Use the following spectrum analyzer settings: Span = zero span, centered on a hopping channel; RBW = 1 MHz; VBW ≥ RBW; Sweep = as necessary to capture the entire dwell time per hopping channel; Detector function = peak; Trace = max hold.
- 6. Measure and record the results in the test report.

3.3.4 Test Setup



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 20 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.3.5 Test Result of Dwell Time

Please refer to Appendix A.

Package Transfer Time Plot Spectrum Ref Level 36.00 dBm Offset 6.00 dB @ RBW 1 MHz Att 40 dB 🍙 SWT 10 ms 🁄 **VBW** 1 MHz ●1Pk Max 3.67 d 3.7768 m D3[1] 30 dBn M1[1] 9.36 dBr 20 dBn 10 dBm -10 dBm -20 dBm -30 dBm 40 **beri**141 -50 dBm -60 dBm CF 2.441 GHz 691 pts 1.0 ms/ Marker Type | Ref | Trc Y-value Function Function Result -value 1.2101 ms 2.9072 ms 3.7768 ms 9.36 dBm 0.40 dB 3.67 dB D2 D3

Date: 26.SEP.2022 23:32:41

Remark:

In normal mode, hopping rate is 1600 hops/s with 6 slots (5 Transmit and 1 Receive slot)
 in 79 hopping channels.

With channel hopping rate (1600 / 6 / 79) in Occupancy Time Limit (0.4×79) (s), Hops Over Occupancy Time comes to $(1600 / 6 / 79) \times (0.4 \times 79) = 106.67$ hops.

- 2. In AFH mode, hopping rate is 800 hops/s with 6 slots in 20 hopping channels.
 With channel hopping rate (800 / 6 / 20) in Occupancy Time Limit (0.4 x 20) (s),
 Hops Over Occupancy Time comes to (800 / 6 / 20) x (0.4 x 20) = 53.33 hops.
- 3. Dwell Time(s) = Hops Over Occupancy Time (hops) x Package Transfer Time

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 21 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.4 20dB and 99% Bandwidth Measurement

3.4.1 Limit of 20dB and 99% Bandwidth

Reporting only

3.4.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.4.3 Test Procedures

- 1. The testing follows ANSI C63.10-2013 clause 6.9.2 and 6.9.3.
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Use the following spectrum analyzer settings for 20dB Bandwidth measurement.

Span = approximately 2 to 5 times the 20 dB bandwidth, centered on a hopping channel;

The RBW is set to 1% to 5% of the 99% OBW, the VBW is set to 3 times the RBW;

Sweep = auto; Detector function = peak;

Trace = max hold.

5. Use the following spectrum analyzer settings for 99 % Bandwidth measurement.

Span = approximately 1.5 to 5 times the 99% bandwidth, centered on a hopping channel;


The RBW is set to 1% to 5% of the 99% OBW, the VBW is set to 3 times the RBW;

Sweep = auto; Detector function = sample;

Trace = max hold.

6. Measure and record the results in the test report.

3.4.4 Test Setup



Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 22 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

3.4.5 Test Result of 20dB Bandwidth

Please refer to Appendix A.

<1Mbps>

20 dB Bandwidth Plot on Channel 00



Date: 8.OCT.2022 00:55:29

20 dB Bandwidth Plot on Channel 39



Date: 8.OCT.2022 01:03:03

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 23 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


20 dB Bandwidth Plot on Channel 78



Date: 8.OCT.2022 01:09:48

<2Mbps>

20 dB Bandwidth Plot on Channel 00




Date: 8.OCT.2022 01:44:52

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 24 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

20 dB Bandwidth Plot on Channel 39



Date: 8.OCT.2022 01:50:59

20 dB Bandwidth Plot on Channel 78



Date: 8.OCT.2022 01:58:04

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 25 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<3Mbps>

20 dB Bandwidth Plot on Channel 00



Date: 8.OCT.2022 02:05:41

20 dB Bandwidth Plot on Channel 39



Date: 8.OCT.2022 02:13:56

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 26 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

20 dB Bandwidth Plot on Channel 78



Date: 8.OCT.2022 02:29:46

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 27 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.4.6 Test Result of 99% Occupied Bandwidth

Please refer to Appendix A.

<1Mbps>

99% Occupied Bandwidth Plot on Channel 00



Date: 8.OCT.2022 00:56:53

99% Occupied Bandwidth Plot on Channel 39



Date: 8.OCT.2022 01:04:29

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4

Page Number : 28 of 59 Report Issued Date: Nov. 10, 2022 Report Version : Rev. 01

Report No.: FR292212A

99% Occupied Bandwidth Plot on Channel 78



Date: 8.OCT.2022 01:11:05

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 29 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<2Mbps>

99% Occupied Bandwidth Plot on Channel 00



Date: 8.OCT.2022 01:46:32

99% Occupied Bandwidth Plot on Channel 39




Date: 8.OCT.2022 01:52:46

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 30 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

99% Occupied Bandwidth Plot on Channel 78



Date: 8.OCT.2022 01:59:29

<3Mbps>

99% Occupied Bandwidth Plot on Channel 00



Date: 8.OCT.2022 02:06:47

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 31 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

99% Occupied Bandwidth Plot on Channel 39



Date: 8.OCT.2022 02:15:04

99% Occupied Bandwidth Plot on Channel 78



Note: The occupied channel bandwidth is maintained within the band of operation for all of the modulations.

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 32 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.5 Output Power Measurement

3.5.1 Limit of Output Power

The maximum peak conducted output power of the intentional radiator shall not exceed the following: (1) For frequency hopping systems operating in the 2400-2483.5 MHz band employing at least 75 non-overlapping hopping channels, and all frequency hopping systems in the 5725-5850 MHz band: 1 watt. For all other frequency hopping systems in the 2400-2483.5 MHz band 0.125 watts. The power limit for 1Mbps, 2Mbps, 3Mbps and AFH modes are 0.125 watts.


3.5.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.5.3 Test Procedures

- 1. The testing follows ANSI C63.10-2013 clause 7.8.5.
- 2. The RF output of EUT was connected to the power meter by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Measure the conducted output power with cable loss and record the results in the test report.
- 5. Measure and record the results in the test report.

3.5.4 Test Setup



3.5.5 Test Result of Peak Output Power

Please refer to Appendix A.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 33 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.6 Conducted Band Edges Measurement

3.6.1 Limit of Band Edges

In any 100 kHz bandwidth outside the intentional radiation frequency band, the radio frequency power shall be at least 20 dB below the highest level of the radiated power. In addition, radiated emissions which fall in the restricted bands must also comply with the radiated emission limits.


3.6.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.6.3 Test Procedures

- 1. The testing follows ANSI C63.10-2013 clause 7.8.6.
- 2. Set to the maximum power setting and enable the EUT transmit continuously.
- Set RBW = 100kHz, VBW = 300kHz. Band edge emissions must be at least 20 dB down from the highest emission level within the authorized band as measured with a 100kHz RBW. The attenuation shall be 30 dB instead of 20 dB when RMS conducted output power procedure is used.
- 4. Enable hopping function of the EUT and then repeat step 2. and 3.
- 5. Measure and record the results in the test report.

3.6.4 Test Setup




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 34 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.6.5 Test Result of Conducted Band Edges


<1Mbps>

Low Band Edge Plot on Channel 00



Date: 8.OCT.2022 00:56:05

High Band Edge Plot on Channel 78




Date: 25.0CT.2022 10:38:52

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 35 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<2Mbps>

Low Band Edge Plot on Channel 00



Date: 8.OCT.2022 01:45:55

High Band Edge Plot on Channel 78



Date: 8.OCT.2022 01:58:48


Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 36 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<3Mbps>

Low Band Edge Plot on Channel 00



Date: 8.OCT.2022 02:06:07

High Band Edge Plot on Channel 78



Date: 8.OCT.2022 02:30:08

Sporton International Inc. (Kunshan)


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 37 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.6.6 Test Result of Conducted Hopping Mode Band Edges

<1Mbps>

Hopping Mode Low Band Edge Plot



Date: 8.OCT.2022 00:59:48

Hopping Mode High Band Edge Plot



Date: 8.OCT.2022 01:22:12


Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 38 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<2Mbps>

Hopping Mode Low Band Edge Plot



Date: 8.OCT.2022 01:51:54

Hopping Mode High Band Edge Plot



Date: 8.OCT.2022 02:03:21


Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 39 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<3Mbps>

Hopping Mode Low Band Edge Plot



Date: 8.OCT.2022 02:04:44

Hopping Mode High Band Edge Plot



Date: 8.OCT.2022 02:38:42

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 40 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.7 Conducted Spurious Emission Measurement

3.7.1 Limit of Spurious Emission Measurement

In any 100 kHz bandwidth outside the intentional radiation frequency band, the radio frequency power shall be at least 20 dB below the highest level of the radiated power. In addition, radiated emissions which fall in the restricted bands must also comply with the radiated emission limits.


3.7.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.7.3 Test Procedure

- 1. The testing follows ANSI C63.10-2013 clause 7.8.8.
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Set RBW = 100 kHz, VBW = 300kHz, scan up through 10th harmonic. All harmonics / spurs must be at least 20 dB down from the highest emission level within the authorized band as measured with a 100 kHz RBW.
- 5. Measure and record the results in the test report.
- 6. The RF fundamental frequency should be excluded against the limit line in the operating frequency band.

3.7.4 Test Setup



Sporton International Inc. (Kunshan)
TEL: +86-512-57900158


FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 41 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A

3.7.5 Test Result of Conducted Spurious Emission


<1Mbps>

CSE Plot on Ch 00 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 00:57:38

CSE Plot on Ch 00 between 2 GHz ~ 25 GHz




Date: 8.OCT.2022 00:58:05

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 42 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

CSE Plot on Ch 39 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 01:05:15

CSE Plot on Ch 39 between 2 GHz ~ 25 GHz




Date: 8.OCT.2022 01:05:49

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 43 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

CSE Plot on Ch 78 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 01:14:46

CSE Plot on Ch 78 between 2 GHz ~ 25 GHz




Date: 8.OCT.2022 01:15:27

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 44 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<2Mbps>

CSE Plot on Ch 00 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 01:47:06

CSE Plot on Ch 00 between 2 GHz ~ 25 GHz




Date: 8.OCT.2022 01:47:37

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 45 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

CSE Plot on Ch 39 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 01:53:23

CSE Plot on Ch 39 between 2 GHz ~ 25 GHz




Date: 8.OCT.2022 01:53:52

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 46 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

CSE Plot on Ch 78 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 02:00:17

CSE Plot on Ch 78 between 2 GHz ~ 25 GHz




Date: 8.OCT.2022 02:00:51

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 47 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A


<3Mbps>

CSE Plot on Ch 00 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 02:08:43

CSE Plot on Ch 00 between 2 GHz ~ 25 GHz




Date: 8.OCT.2022 02:09:32

Sporton International Inc. (Kunshan)

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 48 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01


Report No.: FR292212A

CSE Plot on Ch 39 between 30MHz ~ 3 GHz



Date: 8.OCT.2022 02:26:08

CSE Plot on Ch 39 between 2 GHz ~ 25 GHz



Date: 8.OCT.2022 02:26:37

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: IHDT56AH4 Page Number : 49 of 59
Report Issued Date : Nov. 10, 2022
Report Version : Rev. 01

Report No.: FR292212A