



**MOTOROLA**

**Date:** October 26, 2006

**Subject:** Request for additional information regarding FCC ID: IHDT56GD1

**Reference:**

Correspondence Reference Number:	IHD0615
Confirmation Number:	1610020614/0616
Date of Original Email:	October 25, 2006

**Prepared by:**

Andrew Bachler, Principal Staff Engineer  
Motorola Mobile Device Business  
Libertyville, Illinois

Questions and responses follow:

1. There appears to be a typo on either page 7 or page 8 of the EMC report regarding the ERP level for the WCDMA mode.

**Response:** The corrected values for page 7 follow:

WCDMA 850:

<u>Frequency</u>	<u>ERP</u>
826.4 MHz	23.12 dBm
836.0 MHz	22.23 dBm
846.6 MHz	23.14 dBm

2. Sample label exhibit 1 appears to need revision.

**Response:** Please refer to the revised exhibit 1 submitted Oct 12, 2006.

3. Please verify that the statement required by Section 15.19 and 15.105 of the Rules will be included in the user's manual prior to shipment of the EUT.

**Response:** Confirmed. The required Part 15 statements will be included in the final version of the user's manual.

4. Please address WCDMA 3G issues in the EMC and SAR reports. Submit a statement of the mode used for final measurements.

**Response:** The FCC May/June 2006 guidance for WCDMA was followed. Conducted power levels follow:

Conducted power (dBm) for WCDMA modes			
	Channel	RMC	AMR
WCDMA	4132	24.05	24.08
850	4180	23.83	23.83
	4233	24.35	24.34