



MOTOROLA

Date: April 16, 2007

Subject: Request for additional information regarding FCC ID: IHDT56HP1

Reference:

Correspondence Reference Number:	IHD7264
Confirmation Number:	704020264-66
Date of Original Email:	April 10, 2007

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois

Question and response follow:

Bluetooth Radiated Report (Exhibit 6A2) indicates chase Log-Periodic Antenna and UL 40GHz BOMS Signal Path equipments are out of calibration on Page 4 with respect to the test dates indicated within the report and data. Please explain or re-test as necessary.

Response: Please refer to the updated Bluetooth Radiated Report (Exhibit 6A2) submitted on April 16, 2007. The earlier report specified the wrong antenna. The correct antenna used was Schaffner 6109 S/N 22987, calibrated 08-19-2006. The BOMS signal path is characterized and does not require calibration. It was removed from the equipment list in the updated report.