

Date: March 30, 2007

Subject: Request for additional information regarding FCC ID: IHDT56HY1

Reference: Correspondence Reference Number: Confirmation Number: Date of Original Email:

IHD7134 702260134 March 29, 2007

Prepared by: Andrew Bachler, Principal Staff Engineer Motorola Mobile Device Business Libertyville, Illinois

Questions and responses follow:

1. Signal Generator HP8648C in the SAR Report shows equipment that may have been out of cal during the period of testing. Please address.

Response: When used during the testing process, the equipment met the cal date requirements. (Signal generator HP8648C, SN 38474630 was used on February 27 & 28. The second HP8648C Signal generator in the equipment table, SN3847A04840, was used on March 7.)