

Report No.: HA922117B



HEARING AID COMPATIBILITY T-COIL TEST REPORT

FCC ID : IHDT56YA3

Equipment: Mobile Cellular Phone

Brand Name : Motorola

T-Rating : T3

Applicant : Motorola Mobility LLC

222 W, Merchandise Mart Plaza,

Chicago IL 60654 USA

Manufacturer : Motorola Mobility LLC

222 W, Merchandise Mart Plaza,

Chicago IL 60654 USA

Standard : FCC 47 CFR §20.19

ANSI C63.19-2011

The product was received on Mar. 04, 2019 and testing was started from Mar. 11, 2019 and completed on Apr. 17, 2019. We, SPORTON INTERNATIONAL INC., would like to declare that the tested sample has been evaluated in accordance with the test procedures and has been in compliance with the applicable technical standards.

The report must not be used by the client to claim product certification, approval, or endorsement by TAF or any agency of government.

The test results in this variant report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL INC. EMC & Wireless Communications Laboratory, the test report shall not be reproduced except in full.

Approved by: Cona Huang / Deputy Manager

Qua Grang.

SPORTON INTERNATIONAL INC. EMC & Wireless Communications Laboratory

No. 52, Huaya 1st Rd., Guishan Dist., Taoyuan City, Taiwan (R.O.C.)

TEL: 886-3-327-3456 Page: 1 of 25 FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

Table of Contents

Report No.: HA922117B

Page: 2 of 25

Issued Date : Apr. 24, 2019

1.	Attest	tation of Test Results								
2.		ral Information								
3.	Testing Location									
4.		ed Standards								
5.	Air Int	terface and Operating Mode	7							
6.	Measu	urement standards for T-Coil	8							
	6.1	Frequency Response	8							
	6.2	T-Coil Signal Quality Categories	8							
7.	T-Coil	Test Procedure								
	7.1	Test Flow Chart	10							
	7.2	Test Setup Diagram	11							
	7.3	Description of EUT Test Position								
8.	Test E	Equipment List	14							
9.	T-Coil	testing for CMRS Voice	15							
	9.1	GSM Tests Results	15							
	9.2	UMTS Tests Results	16							
	9.3	CDMA Tests Results	16							
10.	T-Coil	testing for CMRS IP Voice	17							
	10.1	VoLTE Tests Results	17							
	10.2	VoWiFi Tests Results	19							
11.	T-Coil	testing for OTT VoIP Application	21							
		rtainty Assessment								
13.	Refere	ences	25							

Appendix A. Plots of T-Coil Measurement Appendix B. DASY Calibration Certificate

History of this test report

Report No.: HA922117B

Report No.	Version	Description	Issued Date
HA922117B	Rev. 01	Initial issue of report	Apr. 24, 2019

TEL: 886-3-327-3456 Page: 3 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

1. Attestation of Test Results

Air Interface	Day J. Miller	T Define	Frequency	Magnetic
All litteriace	Band MHz	T-Rating	Response	Intensity
	GSM850	T3	Pass	Pass
GSM CMRS Voice	GSM1900	T4	Pass	Pass
	EDGE850	T3	Pass	Pass
OTT over EDGE	EDGE1900	T3	Pass	Pass
	Band 2	T4	Pass	Pass
UMTS CMRS Voice	Band 4	T4	Pass	Pass
	Band 5	T4	Pass	Pass
	Band 2	T4	Pass	Pass
OTT over UMTS	Band 4	T4	Pass	Pass
	Band 5	T4	Pass	Pass
	BC0	T4	Pass	Pass
CDMA CMRS Voice	BC1	T4	Pass	Pass
	BC10	T4	Pass	Pass
	BC0	T4	Pass	Pass
OTT over CDMA	BC1	T4	Pass	Pass
	BC10	T4	Pass	Pass
	Band 2	T4	Pass	Pass
	Band 4	T4	Pass	Pass
	Band 5	T4	Pass	Pass
	Band 12	T4	Pass	Pass
VoLTE	Band 25	T4	Pass	Pass
	Band 26	T4	Pass	Pass
	Band 66	T4	Pass	Pass
	Band 71	T4	Pass	Pass
	Band 41	T3	Pass	Pass
OTTITE	Band 66	T3	Pass	Pass
OTT over LTE	Band 41	T3	Pass	Pass
	2450	T3	Pass	Pass
	5200	T3	Pass	Pass
VoWiFI	5300	T3	Pass	Pass
	5500	T3	Pass	Pass
	5800	T3	Pass	Pass
OTT overWiFi	2450	T3	Pass	Pass
OTT over WiFi	5500	T3	Pass	Pass
Date Tested		2019/03/1	1 ~ 2019/04/17	

Report No.: HA922117B

The device is compliance with HAC limits specified in guidelines FCC 47CFR §20.19 and ANSI Standard ANSI C63.19.

Reviewed by: <u>Jason Wang</u> Report Producer: <u>Wan Liu</u>

TEL: 886-3-327-3456 Page: 4 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

2. General Information

Product Feature & Specification
Motorola Mobility LLC
Mobile Cellular Phone
Motorola
IHDT56YA3
88941-1-12
fastboot_surfna_t_oem_t_userdebug_9_PCB29.7_0446_intcfg-test-keys_t
Identical Prototype
GSM850: 824.2 MHz ~ 848.8 MHz GSM1900: 1850.2 MHz ~ 1909.8 MHz WCDMA Band II: 1852.4 MHz ~ 1907.6 MHz WCDMA Band IV: 1712.4 MHz ~ 1752.6 MHz WCDMA Band V: 826.4 MHz ~ 846.6 MHz CDMA2000 BC0: 824.7 MHz ~ 848.31 MHz CDMA 2000 BC1: 1851.25 MHz ~ 1908.75 MHz CDMA 2000 BC1: 1851.25 MHz ~ 1908.75 MHz CDMA 2000 BC10: 817.9 MHz ~ 823.1 MHz LTE Band 2: 1850.7 MHz ~ 1909.3 MHz LTE Band 4: 1710.7 MHz ~ 1754.3 MHz LTE Band 5: 824.7 MHz ~ 848.3 MHz LTE Band 12: 699.7 MHz ~ 715.3 MHz LTE Band 25: 1850.7 MHz ~ 1914.3 MHz LTE Band 26: 814.7 MHz ~ 848.3 MHz LTE Band 26: 814.7 MHz ~ 848.3 MHz LTE Band 66: 1710.7 MHz ~ 1779.3 MHz LTE Band 71: 665.5 MHz ~ 2687.5 MHz LTE Band 71: 665.5 MHz ~ 695.5 MHz WLAN 2.4GHz Band: 5180 MHz ~ 2462 MHz WLAN 5.3GHz Band: 5500 MHz ~ 5320 MHz WLAN 5.5GHz Band: 5500 MHz ~ 5720 MHz WLAN 5.8GHz Band: 5745 MHz ~ 5825 MHz Bluetooth: 2402 MHz ~ 2480 MHz
GSM/GPRS/EGPRS AMR / RMC 12.2Kbps HSDPA HSUPA DC-HSDPA CDMA2000 : 1xRTT/1xEv-Do(Rel.0)/1xEv-Do(Rev.A) LTE: QPSK, 16QAM, 64QAM 802.11a/b/g/n HT20/HT40/VHT20 Bluetooth BR/EDR/LE

Report No.: HA922117B

1. There are two battery options, for T-coil evaluation is selected battery1 as the main test, battery2 choose worst air interface to be tested.

Battery Option								
Battery 1	Brand Name	ATL	Model Name	KE40				
Battery 2	Brand Name	Sunwoda	Model Name	KE40				

TEL: 886-3-327-3456 Page: 5 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

3. Testing Location

Sporton Lab is accredited to ISO 17025 by Taiwan Accreditation Foundation (TAF code: 1190) and the FCC designation No. TW1190 under the FCC 2.948(e) by Mutual Recognition Agreement (MRA) in FCC test.

Report No.: HA922117B

Testing Laboratory						
Test Site	SPORTON INTERNATIONAL INC.					
Test Site Location	No. 52, Huaya 1st Rd., Guishan Dist., Taoyuan City, Taiwan (R.O.C.) TEL: +886-3-327-3456 FAX: +886-3-328-4978					
Test Site No.	Sporton Site No.: SAR04-HY					

4. Applied Standards

- FCC CFR47 Part 20.19
- ANSI C63.19 2011-version
- FCC KDB 285076 D01 HAC Guidance v05
- FCC KDB 285076 D02 T Coil testing v03
- FCC KDB 285076 D03 HAC FAQ v01

TEL: 886-3-327-3456 Page: 6 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

5. Air Interface and Operating Mode

Air Interface	Band MHz	Туре	C63.19 Tested	Simultaneous Transmitter	Name of Voice Service	Power Reduction																									
	GSM850	VO	Yes	WLAN, BT	CMPS Vaiga	No																									
0014	GSM1900	٧٥	res	WLAN, BT	CIVIRS VOICE	No																									
GSM	EDGE850	VD	Yes	WLAN, BT	Coogle Due ⁽¹⁾	No																									
	EDGE1900	٧D	168	WLAN, DI	Google Duo	INO																									
	850			WLAN, BT		No																									
UMTS	1750	VO	Yes	WLAN, BT	CMRS Voice	No																									
UIVITS	1900			WLAN, BT		Service Reduction MRS Voice No No No ogle Duo(1) No MRS Voice No No No ogle Duo(1) No No No ogle Duo(1) No No No No No No No No No No No VoLTE No No No VoLTE No ogle Duo(1) No No No VoWiFi(1) No No No																									
	HSPA	VD	Yes	WLAN, BT	Google Duo ⁽¹⁾	No																									
	850	VO	Vaa	WLAN, BT	CMDC Vains	No																									
CDMA	1900	VO	Yes	WLAN, BT	CIVIRS VOICE	No																									
	EVDO	VD	Yes	WLAN, BT	Google Duo ⁽¹⁾	No																									
	Band 2			WLAN, BT		No																									
	Band 4			WLAN, BT		No																									
	Band 5			WLAN, BT		No																									
LTE	Band 12	VD	\/D	VD Vos	Yes -	Yes	Yes	VD Yes	WLAN, BT	VoLTE	No																				
(FDD)	Band 25	۷۵	Yes	Yes					163	163	163	163	163	165	162	165	165	163	163	163	169	169	165	162	169	165	162	162	162	WLAN, BT	Google Duo ⁽¹⁾
	Band 26							WLAN, BT		No																					
	Band 66			WLAN, BT		No																									
	Band 71			WLAN, BT		No																									
LTE (TDD)	Band 41	VD	Yes	WLAN, BT	VoLTE / Google Duo ⁽¹⁾	No																									
	2450				•	No																									
	5200				VoWiFi ⁽¹⁾	No																									
Wi-Fi	5300	VD	Yes	GSM,WCDMA,CDMA,LTE	1	No N																									
	5500				Google Duo ⁽¹⁾	No																									
	5800					No																									
BT	2450	DT	No	GSM,WCDMA,CDMA,LTE	NA	No																									

Report No.: HA922117B

Type Transport:

VO= Voice only DT= Digital Transport only (no voice)

VD= CMRS and IP Voice Service over Digital Transport

Remark:

- For protocols not listed in Table 7.1 of ANSI C63.19-2011 or the ANSI C63.19-2011 VoLTE interpretation, the average speech level of -20 dBm0 should be used.
- The device have similar frequency in some LTE bands: LTE B5/26, 4/66, 2/25, since the supported frequency spans for the smaller LTE bands are completely cover by the larger LTE bands, therefore, only larger LTE bands were required to be tested for hearing-aid compliance.


TEL: 886-3-327-3456 Page: 7 of 25 FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

6. Measurement standards for T-Coil

6.1 Frequency Response


The frequency response of the perpendicular component of the magnetic field, measured in 1/3 octave bands, shall follow the response curve specified in this sub-clause, over the frequency range 300 Hz to 3000 Hz. Figure 1.1 and Figure 1.2 provide the boundaries as a function of frequency. These response curves are for true field-strength measurements of the T-Coil signal. Thus, the 6 dB/octave probe response has been corrected from the raw readings.

Report No.: HA922117B



NOTE-The frequency response is between 300 Hz and 3000 Hz.

Fig. 1.1 Magnetic field frequency response for WDs with field strength≤-15dB at 1 KHz



NOTE-The frequency response is between 300 Hz and 3000 Hz.

Fig. 1.2 Magnetic field frequency response for WDs with a field that exceeds -15 dB(A/m) at 1 kHz

6.2 T-Coil Signal Quality Categories

This section provides the signal quality requirement for the intended T-Coil signal from a WD. Only the RF immunity of the hearing aid is measured in T-Coil mode. It is assumed that a hearing aid can have no immunity to an interference signal in the audio band, which is the intended reception band for this mode. A device is assessed beginning by determining the category of the RF environment in the area of the T-Coil source.

The RF measurements made for the T-Coil evaluation are used to assign the category T1 through T4. The limitation is given in Table 1. This establishes the RF environment presented by the WD to a hearing aid.

Category	Telephone parameters WD signal quality ((signal + noise) to noise ratio in dB)
Category T1	0 to 10 dB
Category T2	10 to 20 dB
Category T3	20 to 30 dB
Category T4	> 30 dB

Table 1 T-Coil Signal Quality Categories

TEL: 886-3-327-3456 Page: 8 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

7. T-Coil Test Procedure

Referenced to ANSI C63.19-2011, Section 7.4,

This section describes the procedures used to measure the ABM (T-Coil) performance of the WD. In addition to measuring the absolute signal levels, the A-weighted magnitude of the unintended signal shall also be determined. To assure that the required signal quality is measured, the measurement of the intended signal and the measurement of the unintended signal must be made at the same location for each measurement position. In addition, the RF field strength at each measurement location must be at or below that required for the assigned category.

Report No.: HA922117B

Measurements shall not include undesired properties from the WD's RF field; therefore, use of a coaxial connection to a base station simulator or non-radiating load, there might still be RF leakage from the WD, which can interfere with the desired measurement. Pre-measurement checks should be made to avoid this possibility. All measurements shall be performed with the WD operating on battery power with an appropriate normal speech audio signal input level given in ANSI C63.19-2011 Table 7.1. If the device display can be turned off during a phone call, then that may be done during the measurement as well,


Measurement shall be performed at two locations specified in ANSI C63.19-2011 A.3, with the correct probe orientation for a particular location, in a multistage sequence by first measuring the field intensity of the desired T-Coil signal the same location as the desired ABM or T-Coil signal (ABM1), and the ratio of desired to undesired magnetic components (ABM2) must be measured at the same location as the desired ABM or T-Coil signal (ABM1), and the ratio of desired to undesired ABM signals must be calculated. For the perpendicular field location, only the ABM1 frequency response shall be determined in a third measurement stage.

The following steps summarize the basic test flow for determining ABM1 and ABM2. These steps assume that a sine wave or narrowband 1/3 octave signal can be used for the measurement of ABM1.

- a. A validation of the test setup and instrumentation may be performed using a TMFS or Helmholtz coil Measure the emissions and confirm that they are within the specified tolerance.
- b. Position the WD in the test setup and connect the WD RF connector to a base station simulator or a non-radiating load. Confirm that equipment that requires calibration has been calibrated, and that the noise level meets the requirements given in ANSI C63.19-2011 clause 7.3.1.
- c. The drive level to the WD ise set such that the reference input level specified in ANSI C63.19-2011 Table 7.1 is input to the base station simulator (or manufacturer's test mode equivalent) in 1 kHz, 1/3 octave band. This drive level shall be used for the T-Coil signal test (ABM1) at f = 1 kHz. Either a sine wave at 1025 Hz or a voice-like signal, band-limited to the 1 kHz 1/3 octave, as defined in ANSI C63.19-2011 clause 7.4.2, shall be used for the reference audio signal. If interference is found at 1025 Hz an alternative nearby reference audio signal frequency may be used. The same drive level shall be used for the ABM1 frequency response measurements at each 1/3 octave band center frequency. The WD volume control may be set at any level up to maximum, provided that a signal at any frequency at maximum modulation would not result in clipping or signal overload.
- d. Determine the magnetic measurement locations for the WD device (A.3), if not already specified by the manufacturer, as described in ANSI C63.19-2011 clause 7.4.4.1.1 and 7.4.4.2.
- e. At each measurement location, measure and record the desired T-Coil magnetic signals (ABM1 at fi) as described in ANSI C63.19-2011 clause 7.4.4.2 in each individual ISO 266-1975 R10 standard 1/3 octave band. The desired audio band input frequency (fi) shall be centered in each 1/3 octave band maintaining the same drive level as determined in item c) and the reading taken for that band.
- f. Equivalent methods of determining the frequency response may also be employed, such as fast Fourier transform (FFT) analysis using noise excitation or input-output comparison using simulated speech. The full-band integrated probe output, as specified in D.9, may be used, as long as the appropriate calibration curve is applied to the measured result, so as to yield an accurate measurement of the field magnitude. (The resulting measurement shall be an accurate measurement in dB A/m.)
- g. All Measurements of the desired signal shall be shown to be of the desired signal and not of an undesired signal. This may be shown by turning the desired signal ON and OFF with the probe measuring the same location. If the scanning method is used the scans shall show that all measurement points selected for the ABM1 measurement meet the ambient and test system noise criteria in ANSI C63.19-2011 clause 7.3.1.
- h. At the measurement location for each orientation, measure and record the undesired broadband audio magnetic signal (ABM2) as specified in ANSI C63.19-2011 clause 7.4.4.4 with no audio signal applied (or digital zero applied, if appropriate) using A-weighting and the half-band integrator. Calculate the ratio of the desired to undesired signal strength (i,e., signal quality).
- i. Obtain the data from the postprocessor, SEMCAD, and determine the category that properly classifies the signal quality based on ANSI C63.19-2011 Table 8.5.

TEL: 886-3-327-3456 Page: 9 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

7.1 Test Flow Chart




Report No.: HA922117B

Fig. 2 T-Coil Signal Test flowchart

TEL: 886-3-327-3456 Page: 10 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

7.2 Test Setup Diagram



Report No.: HA922117B

General Note:

- 1. Define the all applicable input audio level as below according to C63 and KDB 285076 D02v03:
 - GSM input level: -16dBm0
 - UMTS input level: -16dBm0
 - CDMA input level: -18dBm0
 - VoLTE input level: -16dBm0
 - VoWiFi input level: -20dBm0
 - OTT VoIP input Level: -20dBm0
- 2. For GSM / UMTS / CDMA test setup and input level, the correct input level definition is via a communication tester CMU200's "Decoder Cal" and "Codec Cal" with audio option B52 and B85 to set the correct audio input levels.
- 3. CMU200 is able to output 1kHz audio signal equivalent to 3.14dBm0 at "Decoder Cal." confuguration, the signal reference is used to adjust the AMMI gain setting to reach -16dBm0 for GSM/UMTS and -18dBm0 for CDMA. CMW500 input is calibrated and the relation between the analog input voltage and the internal level in dBm0 can be determined
- 4. The test setup used for VoLTE over IMS and VoWiFi over IMS is via the callbox of CMW500 for T-coil measurement, The data application unit of the CMW500 was used to simulate the IP multimedia subsystem server. The CMW500 can be manually configured to ensure and control the speech input level result is -16dBm0 for VoLTE, -20dBm0 for VoWiFi when the device during the IMS connection.
- 5. The test setup used for Google DUO VoIP call is via the data application unit on CMW500 connection to the Internet, also connection to the other auxiliary VoIP unit which is used to configure the audio codec and bit rate and also monitor the audio input level of -20dBm0.

TEL: 886-3-327-3456 Page: 11 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019



SPORTON LAB. HAC T-COIL TEST REPORT

 The Required gain factor for the specific signal shall typically be multiplied by this factor to achieve approx. the same level as for the 1kHz sine signal

Report No.: HA922117B

2. The below calculation formula is an example and showing how to determine the input level for the device.

The predefined signal types have the following differences / factors compared to the 1kHz sine signal:

Signal [file name]	Duration [s]	Peak-to- RMS [dB]	RMS [dB]	Required gain factor *)	Gain setting
1kHz sine		3.0	0.0	1.00	
48k_1.025kHz_10s.wav	10	3.0	0.0	1.00	
48k_1kHz_3.15kHz_10s.wav	10	6.0	-3.0	1.42	
48k_315Hz_1kHz_10s.wav	10	6.0	-2.9	1.40	
48k csek 8k 441 white 10s.wav	10	13.8	-10.5	3.34	
48k_multisine_50-5000_10s.wav	10	11.1	-7.9	2.49	
48k_voice_1kHz_1s.wav	1	16.2	-12.7	4.33	
48k voice 300-3000 2s.wav	2	21.6	-18.6	8.48	

(*) The gain for the specific signal shall typically be multiplied by this factor to acheive approx. the same level as for the 1kHz sine signal.

Insert the gain applicable for your setup in the last column of the table.

Calculation formula:

- Audio Level at -16dBm0 = ((-16dBm0) (3.14dBm0)) + X dBv
- Calculated Gain at -16dBm0 = 10((audio level at -16dBm0 Y dBm0) / 20) * 10

- Gatting setting at -16dBm0 = required gain factor * calculated gain

Gain Value	Gain Value 20* log(gain)		Level				
(linear)	(linear) dB		dBm0				
		-2.47	3.14				
10	20	-19.85	-14.24				
8.17	18.24	-21.61	-16				

Signal Type	Duration (s)	Peak to RMS (dB)	RMS (dB)	Required Gain Factor	Calculated Gain Setting
1kHz sine	-	3	0	1	8.17
48k_voice_1kHz	1	16.2	-12.7	4.33	35.36
48k_voice_300Hz ~ 3kHz	2	21.6	-18.6	8.48	69.25

TEL: 886-3-327-3456 Page: 12 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

7.3 Description of EUT Test Position

Fig.3 illustrate the references and reference plane that shall be used in a typical EUT emissions measurement. The principle of this section is applied to EUT with similar geometry. Please refer to Appendix C for the setup photographs.

Report No.: HA922117B

- ♦ The area is 5 cm by 5 cm.
- ♦ The area is centered on the audio frequency output transducer of the EUT.
- ◆ The area is in a reference plane, which is defined as the planar area that contains the highest point in the area of the phone that normally rests against the user's ear. It is parallel to the centerline of the receiver area of the phone and is defined by the points of the receiver-end of the EUT handset, which, in normal handset use, rest against the ear.
- ◆ The measurement plane is parallel to, and 10 mm in front of, the reference plane.




Fig.3 A typical EUT reference and plane for T-Coil measurements

TEL: 886-3-327-3456 Page: 13 of 25 FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

8. Test Equipment List

Manufacturer	Name of Equipment	Type/Medal	Serial Number	Calib	ration
Manuracturer	Name of Equipment	Type/Model	Serial Number	Last Cal.	Due Date
SPEAG	Audio Magnetic 1D Field Probe	AM1DV3	3130	Nov. 20, 2018	Nov. 19, 2019
SPEAG	Data Acquisition Electronics	DAE4	854	Jun. 14, 2018	Jun. 13, 2019
SPEAG	Data Acquisition Electronics	DAE4	918	Jun. 20, 2018	Jun. 19, 2019
SPEAG	Audio Magnetic Calibration Coil	AMCC	1049	NCR	NCR
SPEAG	Audio Measuring Instrument	AMMI	1041	NCR	NCR
SPEAG	Test Arch Phantom	N/A	N/A	NCR	NCR
SPEAG	Phone Positioner	N/A	N/A	NCR	NCR
TESTO	Hygro meter	608-H1	34913631	Aug. 27, 2018	Aug. 26, 2019
R&S	Base Station	CMW500	115793	May. 24, 2018	May. 23, 2019
R&S	Base Station	CMU200	116457	May. 30, 2018	May. 29, 2019

Report No.: HA922117B

Note:

TEL: 886-3-327-3456 Page: 14 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

^{1.} NCR: "No-Calibration Required"

9. T-Coil testing for CMRS Voice

General Note:

1. <u>Codec Investigation:</u> For a voice service/air interface, investigate the variations of codec configurations (WB, NB bit rate) and document the parameters (ABM1, ABM2, S+N/N, frequency response) for that voice service. It is only necessary to document this for one channel/band, the following worst investigation codec would be remarked to be used for the testing for the handset.

2. Air Interface Investigation:

a. Use the worst-case codec test and document a limited set of bands/channel/bandwidths. Observe the effect of changing the band and bandwidth to ensure that there are no unexpected variations. Using the knowledge of the observed variations, it is necessary to report only a set band/channel/bandwidth for each orientation for a voice service/air interface.

Report No.: HA922117B

b. According to the ANSI C63.19 2011 section 7.3.2, test middle channel of each frequency band for HAC testing for each orientation to determine worst HAC T-Coil rating.

9.1 GSM Tests Results

<Codec Investigation>

Codec	FR_V1	HR_V1	Orientation	Band / Channel
ABM 1 (dBA/m)	-2.93	-2.98		
ABM 2 (dBA/m)	-27.19	-30.4	Axial	CCM050 / 400
Signal Quality (dB)	24.26	27.42	Axiai	GSM850 / 189
Freq. Response	Pass	Pass		

Remark: According to codec investigation, the worst codec is FR_V1

<Air Interface Investigation>

Plot No.	Air Interface	Mode	Channel	Battery		ABM1 dB (A/m)	dB	Signal Quality dB	T Rating	Ambient Noise dB (A/m)	Response	Frequency Response	
1	GSM850	Voice	190	Potton/1	Axial (Z)	-2.93	-27.19	24.26	T3	-50.36	1.78	Pass	
	GSIVIOSO	voice	189	Battery1	Dallery	Transversal (Y)	-11.14	-40.14	29.00	T3	-50.21	1.70	F 455
2	GSM1900	Voice	661	Battery1	Axial (Z)	-3.92	-38.45	34.53	T4	-50.30	2	Pass	
	Z GSW1900 Voice		001	Бацегут	Transversal (Y)	-10.35	-46.78	36.43	T4	-50.18	2	rass	

TEL: 886-3-327-3456 Page: 15 of 25 FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

9.2 UMTS Tests Results

<Codec Investigation>

Codec	AMR 4.75Kbps	AMR 7.95Kbps	AMR 12.2Kbps	Orientation	Band / Channel
ABM 1 (dBA/m)	-3.64	-3.58	3.71		
ABM 2 (dBA/m)	-45.34	-44.16	-36.47	Axial	Band 2 / 9400
Signal Quality (dB)	41.7	40.58	40.18	Axiai	Band 2 / 9400
Freq. Response	Pass	Pass	Pass		

Report No.: HA922117B

Remark: According to codec investigation, the worst codec is AMR 12.2Kbps

<Air Interface Investigation>

Plot No.	Air Interface	Mode	Channel	Battery		dB	ABM2 dB (A/m)	Signal Quality dB	T Rating	Ambient Noise dB (A/m)	Response	Frequency Response
3	WCDMA II	Voice	9400	Rattery/1	Axial (Z)	-3.71	-43.89	40.18	T4	-50.33	1.84	Pass
3	WCDIVIA II	Voice	9400	Battery1	Transversal (Y)	-9.72	-48.55	38.83	T4	-50.20	1.04	rdSS
4	WCDMA IV	Maia	1.112	Datta4	Axial (Z)	-3.62	-43.60	39.98	T4	-50.34	1.79	Pass
4	WCDIVIA IV	Voice	1413	Battery1	Transversal (Y)	-10.19	-48.69	38.50	T4	-50.21	1.79	Pass
-	WCDMA V Voice	4400	Dattand	Axial (Z)	-2.55	-43.31	40.76	T4	-50.33	1.66	D	
5	5 WCDMA V Voice	4182	Battery1	Transversal (Y)	-9.74	-48.75	39.01	T4	-50.21	1.00	Pass	

9.3 CDMA Tests Results

<Codec Investigation>

Codec	RC1 SO68	RC3 SO68	RC4 SO68	Orientation	Band / Channel
ABM 1 (dBA/m)	-3.49	-2.61	-4.38		
ABM 2 (dBA/m)	-46.52	-45.77	-47.37	Axial	BC0 / 384
Signal Quality (dB)	43.03	43.16	42.99	Axiai	BC0 / 364
Freq. Response	Pass	Pass	Pass		

Remark: According to codec investigation, the worst codec is RC4 SO68

<Air Interface Investigation>

Plot No.	Air Interface	Mode	Channel	Battery		dB	ABM2 dB (A/m)	Signal Quality dB		Ambient Noise dB (A/m)	Response	Frequency Response
6	CDMA BC0	RC1+SO68 Voice codec 8K	204	Pottor /1	Axial (Z)	-4.38	-47.37	42.99	T4	-50.35	1.33	Pass
0	CDIVIA BCU	Enhanced low	384	Battery1	Transversal (Y)	-9.14	-47.80	38.66	T4	-50.24	1.33	F 455
	00111 001	RC1+SO68 Voice	000	D // 4	Axial (Z)	-3.86	-46.86	43.00	T4	-50.32	4.07	D
/	CDMA BC1	codec 8K Enhanced low	600	Battery1	Transversal (Y)	-9.16	-47.50	38.34	T4	-50.21	1.27	Pass
•	0DMA D040	RC1+SO68 Voice	500		Axial (Z)	-4.08	-46.97	42.89	T4	-50.31	4.05	D
8	8 CDMA BC10 codec 8K Enhanced low	580	Battery1	Transversal (Y)	-9.94	-48.68	38.74	T4	-50.22	1.25	Pass	

TEL: 886-3-327-3456 Page: 16 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

10. T-Coil testing for CMRS IP Voice

10.1 VoLTE Tests Results

General Note:

Codec Investigation: For a voice service/air interface, investigate the variations of codec configurations (WB, NB bit rate) and document the parameters (ABM1, ABM2, S+N/N, frequency response) for that voice service. It is only necessary to document this for one channel / band, the following worst investigation codec would be remarked to be used for the testing for the handset.

2. Air Interface Investigation:

a. Use the worst-case codec test and document a limited set of bands / channel / bandwidths. Observe the effect of changing the band and bandwidth to ensure that there are no unexpected variations. Using the knowledge of the observed variations, it is necessary to report only a set band/channel/bandwidth for each orientation for a voice service/air interface and the following worst configure would be remarked to be used for the testing for the handset.

Report No.: HA922117B

- b. Select LTE FDD / TDD one frequency band to do measurement at the worst SNR position was additionally performed with varying the BWs/Modulations/RB size to verify the variation to find out worst configuration, the observed variation is very little to be within 1 dB which is much less than the margin from the rating threshold.
- c. The TDD LTE power class 3 supports uplink-downlink configuration 0 and 6 and power class 2 supports uplink-downlink configuration1 to 5 for this device, an investigation was performed to determine the worst-case uplink-downlink configuration to be used for the testing for the handset.
- d. According to the ANSI C63.19 2011 section 7.3.2, test middle channel of each frequency band for HAC testing for each orientation to determine worst HAC T-Coil rating.

<Codec Investigation>

LTE FDD

Codec	NB AMR 4.75Kbps	WB AMR 6.60Kbps	NB AMR 12.2Kbps	WB AMR 23.85Kbps	EVS SWB 9.6Kbps	EVS SWB 128Kbps	EVS WB 5.9Kbps	EVS WB 128Kbps	EVS NB 5.9Kbps	EVS NB 24.4Kbps	Orientation	Band / BW / Channel
ABM 1 (dBA/m)	-0.88	-1.02	-1.93	-2.43	-0.03	-0.47	-1.86	-0.44	-0.71	-1.73		
ABM 2 (dBA/m)	-39.02	-39.06	-40.16	-40.2	-38.91	-38.36	-39.68	-38.48	-38.9	-39.61		B25 / 20M /
Signal Quality (dB)	38.14	38.04	38.23	37.77	38.88	37.89	37.82	38.04	38.19	37.88	Axial	26340
Freq. Response	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass		

Remark: According to codec investigation, the worst codec is WB AMR 23.85Kbps

LTE TDD

Codec	NB AMR 4.75Kbps	WB AMR 6.60Kbps	NB AMR 12.2Kbps	WB AMR 23.85Kbps	EVS SWB 9.6Kbps	EVS SWB 128Kbps	EVS WB 5.9Kbps	EVS WB 128Kbps	EVS NB 5.9Kbps	EVS NB 24.4Kbps	Orientation	Band / BW / Channel
ABM 1 (dBA/m)	-1.41	-1.22	-1.31	-1.4	-0.96	-0.98	-0.89	-0.88	-0.85	-0.89		
ABM 2 (dBA/m)	-31.07	-29.95	-30.85	-31.71	-30.61	-30.49	-30.31	-30.22	-29.91	-29.82	Axial	B41 / 20M /
Signal Quality (dB)	29.66	28.73	29.54	30.31	29.65	29.51	29.42	29.34	29.06	28.93	Axiai	40620
Freq. Response	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass		

Remark: According to codec investigation, the worst codec is WB AMR 6.60Kbps

TEL: 886-3-327-3456 Page: 17 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019



SPORTON LAB. HAC T-COIL TEST REPORT

<Air Interface Investigation>

Air	Interface	BW (MHz)	Modulation	RB Size	RB offset	Channel	UL-DL Configuration	ABM1 dB (A/m)	ABM2 dB (A/m)	Signal Quality dB
	LTE B25	20	QPSK	1	0	26340	-	-1.60	-40.89	39.29
	LTE B25	20	QPSK	50	0	26340	-	-1.54	-41.61	40.07
	LTE B25	20	QPSK	100	0	26340	-	-1.61	-41.68	40.07
	LTE B25	20	16QAM	1	0	26340	-	-1.63	-41.69	40.06
	LTE B25	20	64QAM	1	0	26340	-	-1.48	-41.72	40.24
FDD	LTE B25	15	QPSK	1	0	26340	-	-1.62	-41.04	39.42
	LTE B25	10	QPSK	1	0	26340	-	-1.69	-41.12	39.43
	LTE B25	5	QPSK	1	0	26340	-	-1.66	-41.13	39.47
	LTE B25	3	QPSK	1	0	26340	-	-1.67	-41.16	39.49
	LTE B25	1.4	QPSK	1	0	26340	-	-1.59	-41.60	40.01
	LTE B41_PC3	20	QPSK	1	0	40620	0	-1.04	-31.47	30.43
	LTE B41_PC3	20	QPSK	50	0	40620	0	-1.06	-31.55	30.49
	LTE B41_PC3	20	QPSK	100	0	40620	0	-0.97	-31.54	30.57
	LTE B41_PC3	20	16QAM	1	0	40620	0	-1.01	-31.51	30.50
	LTE B41_PC3	20	64QAM	1	0	40620	0	-0.99	-31.54	30.55
	LTE B41_PC3	15	QPSK	1	0	40620	0	-0.91	-31.52	30.61
	LTE B41_PC3	10	QPSK	1	0	40620	0	-0.95	-31.46	30.51
TDD	LTE B41_PC3	5	QPSK	1	0	40620	0	-0.96	-31.51	30.55
	LTE B41_PC3	20	QPSK	1	0	40620	6	-0.94	-31.43	30.49
	LTE B41_PC2	20	QPSK	1	0	40620	1	-0.92	-31.47	30.55
	LTE B41_PC2	20	QPSK	1	0	40620	2	-0.98	-31.44	30.46
	LTE B41_PC2	20	QPSK	1	0	40620	3	-0.81	-31.41	30.60
	LTE B41_PC2	20	QPSK	1	0	40620	4	-0.89	-31.38	30.49
	LTE B41_PC2	20	QPSK	1	0	40620	5	-0.92	-31.38	30.46

Report No.: HA922117B

Plot No.	Air Interface	BW (MHz)	Modulation	RB Size	RB offset	Channel	Battery	Probe Position	ABM1 dB (A/m)	ABM2 dB (A/m)	Signal Quality dB	T Rating	Ambient Noise dB (A/m)		Frequency Response
9	LTE Band 12	10M	QPSK	1	0	23095	Battery1	Axial (Z)	-2.47	-42.80	40.33	T4	-50.36	1	Pass
	LTE Band 12	TOW	QI OIX		U	20000	Dattery	Transversal (Y)	-8.40	-44.34	35.94	T4	-50.23	•	1 433
10	LTE Band 25	20M	QPSK	1	0	26340	Potton/1	Axial (Z)	-2.43	-40.20	37.77	T4	-50.34	0.9	Pass
10	LTE Dallu 25	ZUIVI	QFSN	'	0	20340	Battery1	Transversal (Y)	-9.87	-45.41	35.54	T4	-50.23	0.9	F455
11	LTC Dand OC	1511	QPSK	1		26965	Dottom 1	Axial (Z)	-0.96	-38.89	37.93	T4	-50.33	0.00	Door
11	LTE Band 26	15M	QPSK	'	0	26865	Battery1	Transversal (Y)	-10.33	-45.88	35.55	T4	-50.20	0.88	Pass
12	LTE Band 41	20M	QPSK	1	0	40620	Pottor/1	Axial (Z)	-1.22	-29.95	28.73	T3	-50.31	0.53	Pass
12	LIE Dallu 41	ZUIVI	QFSN	'	0	40020	Battery1	Transversal (Y)	-11.03	-46.25	35.22	T4	-50.18	0.55	F455
13	LTE Band 66	2014	QPSK	1		122222	Dottom 1	Axial (Z)	-1.55	-39.34	37.79	T4	-50.33	0.00	Door
13	LIE Band 66	20M	QPSK	'	0	132322	Battery1	Transversal (Y)	-8.43	-43.86	35.43	T4	-50.21	0.89	Pass
1.1	LTC Dond 71	2014	QPSK	4	_	122222	Dottom 1	Axial (Z)	-0.34	-39.35	39.01	T4	-50.32	0.49	Door
14	LTE Band 71	20M	QP5K	1	0	133322 B	Battery1	Transversal (Y)	-9.80	-45.62	35.82	T4	-50.24	0.48	Pass

TEL: 886-3-327-3456 Page: 18 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

10.2VoWiFi Tests Results

General Note:

Codec Investigation: For a voice service/air interface, investigate the variations of codec configurations
(WB, NB bit rate) and document the parameters (ABM1, ABM2, S+N/N, frequency response) for that voice service. It
is only necessary to document this for one channel/band, the following worst investigation codec would be remarked
to be used for the testing for the handset.

Report No.: HA922117B

- 2. Air Interface Investigation:
 - a. Use the worst-case codec test and document a limited set of bands/channel/bandwidths. Observe the effect of changing the band and bandwidth to ensure that there are no unexpected variations. Using the knowledge of the observed variations, it is necessary to report only a set band/channel/bandwidth for each orientation for a voice service/air interface and the following worst configure would be remarked to be used for the testing for the handset.
 - b. Select WLAN 2.4GHz and WLAN 5GHz one frequency band to do measurement at the worst SNR position was additionally performed with varying the BWs/Modulations/data rate to verify the variation to find out worst configuration, the observed variation is very little to be within 1 dB which is much less than the margin from the rating threshold.
 - c. According to the ANSI C63.19 2011 section 7.3.2, test middle channel of each frequency band for HAC testing for each orientation to determine worst HAC T-Coil rating.

<Codec Investigation>

Codec	NB AMR 4.75Kbps	WB AMR 6.60Kbps	NB AMR 12.2Kbps	WB AMR 23.85Kbps	EVS SWB 9.6Kbps	EVS SWB 128Kbps	EVS WB 5.9Kbps	EVS WB 128Kbps	EVS NB 5.9Kbps	EVS NB 24.4Kbps	Orientation	Band / Channel
ABM 1 (dBA/m)	-3.42	-4.13	-3.68	-2.82	-3.31	-3.15	-3.14	-2.16	-2.45	-3.04		
ABM 2 (dBA/m)	-40.64	-40.51	-40.86	-40.76	-40.42	-41.27	-41.11	-38.82	-39.54	-41.08		2.4GHz
Signal Quality (dB)	37.22	36.38	37.18	37.94	37.11	38.12	37.97	36.66	37.09	38.04	Axial	WLAN / 6
Freq. Response	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass	Pass		

Remark: According to codec investigation, the worst codec is WB AMR 6.60Kbps

<Air Interface Investigation>

Frequency Bands	Modulation	Bandwidth	Data Rate	Channel	ABM1 dB (A/m)	ABM2 dB (A/m)	Signal Quality dB
	802.11b	20	1M	6	-4.29	-38.64	34.35
	802.11b	20	11 M	6	-3.97	-39.11	35.14
	802.11g	20	6M	6	-3.73	-39.50	35.77
WLAN 2.4GHz	802.11g	20	54M	6	-3.76	-39.08	35.32
WLAN 2.4GHZ	802.11n-HT20	20	MCS0	6	-4.01	-39.24	35.23
	802.11n-HT20	20	MCS7	6	-3.86	-39.11	35.25
	802.11n-HT40	40	MCS0	6	-3.85	-39.79	35.94
	802.11n-HT40	40	MCS7	6	-3.69	-38.44	34.75
	802.11a	20	6M	40	-4.10	-41.13	37.03
	802.11a	20	54M	40	-3.97	-41.12	37.15
WLAN 5GHz	802.11an-HT20	20	MCS0	40	-4.01	-42.10	38.09
WLAN 5GHZ	802.11an-HT20	20	MCS7	40	-4.15	-41.70	37.55
	802.11an-HT40	40	MCS0	38	-4.02	-41.70	37.68
	802.11an-HT40	40	MCS7	38	-3.95	-41.74	37.79

TEL: 886-3-327-3456 Page: 19 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019



Freq. Ambient ABM1 ABM2 Signal Probe Noise Response Frequency Variation Response Plot Quality Air Interface Mode Channel dB dB **Battery** No. Rating **Position** dB (A/m) (A/m) dB (A/m) dB -4.13 -40.51 Axial (Z) 36.38 T4 -50.36 WLAN2.4GHz 802.11b 1Mbps 0.59 6 Battery1 Pass 15 Transversal (Y) -15.46 -38.77 23.31 Т3 -50.26 T4 Axial (Z) -3.82 -38.46 34.64 -50.33 WLAN5GHz 802.11a 6Mbps 40 Battery1 0.52 Pass -14.28 -42.53 28.25 Т3 -50.25 Transversal (Y) Axial (Z) -3.68 37.75 34.07 T4 -50.35 WLAN5GHz 60 17 802.11a 6Mbps Battery1 0.76 **Pass** 13.95 Т3 -43.03 29.08 -50.23 Transversal (Y) -7.32 -46.43 39.11 T4 -50.34 Axial (Z) WLAN5GHz 18 802.11a 6Mbps 124 Battery1 0.61 **Pass** -15.18 -37.57 22.39 Т3 -50.22 Transversal (Y) Axial (Z) -4.79 39.70 34.91 T4 -50.38 WLAN5GHz 19 802.11a 6Mbps 124 Battery2 0.84 Pass -14.92 -50.28 43.07 28.15 Т3 Transversal (Y) T4 Axial (Z) -4.14 -41.42 37.28 -50.35 20 WLAN5GHz 802.11a 6Mbps 0.44 157 Battery1 Pass Transversal (Y) -16.86 -40.89 24.03 Т3 -50.25

Report No.: HA922117B

TEL: 886-3-327-3456 Page: 20 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

11. T-Coil testing for OTT VoIP Application

General Notes:

- According to the ANSI C63.19 2011 section 7.3.2, test middle channel of each frequency band for HAC testing for each orientation to determine worst HAC T-Coil rating.
- 2. The google Duo VoIP application are pre-installed on this device. According to KDB 285076 D02, all air interfaces via a data connection with VoIP application need to be considered HAC testing.

Report No.: HA922117B

- 3. The Google Duo only support OPUS audio codec and support 6Kbps to 75Kbps bitrate.
- 4. The test setup used for OTT VoIP call is the DUT connect to the CMW500 and via the data application unit on CMW500 connection to the Internet, the Auxiliary EUT is connected to the WiFi access point, the channel/Modulation/Frequency bands/data rate is configured on the CMW500 for the DUT unit. For the Auxiliary VoIP unit which is used to configure the audio codec rate and determine the audio input level of -20dBm0 based on the KDB 285076 D02v03 requirement.
- 5. <u>Codec Investigation:</u> For a voice service/air interface, investigate the variations of codec configurations (WB, NB bit rate) and document the parameters (ABM1, ABM2, S+N/N, frequency response) for that voice service. It is only necessary to document this for one channel/band, the following tests results which the worst case codec would be remarked to be used for the testing for the handset.
- 6. Air Interface Investigation:
 - a. Use the worst-case codec test and document a limited set of bands/channel/bandwidths. Observe the effect of changing the band and bandwidth to ensure that there are no unexpected variations. Using the knowledge of the observed variations, it is necessary to report only a set band/channel/bandwidth for each orientation for a voice service/air interface.
 - b. Due to OTT service and CMRS IP service are all be established over the internet protocol for the voice service, and on both services use the identical RF air interface for the WIFI and LTE, therefore according to VoLTE and VoWiFi test results of air interface investigation, the worst configuration and frequency band of air interface was used for OTT T-Coil testing.
 - -LTE FDD worst configuration and band: LTE Band 66/20MHz/QPSK/1RB Size
 - -LTE TDD worst configuration and band: LTE Band 41/20MHz/QPSK/1RB Size
 - -WLAN2.4GHz worst configuration: 802.11b /1Mbps
 - -WLAN5GHz worst configuration and Band: WLAN 5.5GHz /11a/6Mbps

<Codec Investigation>

EDGE

Codec	OPUS Bitrate 6Kbps	OPUS OPUS Bitrate Bitrate 40Kbps 75Kbps		Orientation	Band / Channel		
ABM 1 (dBA/m)	-6.06	-6.21	-6.96				
ABM 2 (dBA/m)	-32.26	-33.01	-32.76	Axial	CCM050 / 400		
Signal Quality (dB)	26.2	26.8	25.8	Axiai	GSM850 / 189		
Freq. Response	Pass	Pass	Pass				

Remark: According to codec investigation, the worst codec bitrate is 75kbps

HSPA

Codec	OPUS Bitrate 6Kbps	OPUS Bitrate 40Kbps	OPUS Bitrate 75Kbps	Orientation	Band / Channel		
ABM 1 (dBA/m)	-7.11	-5.69	-5.69				
ABM 2 (dBA/m)	-43.36	-41.18	-40.49		LIMTO DO / 0400		
Signal Quality (dB)	36.25	35.49	34.8	Axial	UMTS B2 / 9400		
Freq. Response	Pass	Pass	Pass				

Remark: According to codec investigation, the worst codec bitrate is 75kbps

TEL: 886-3-327-3456 Page: 21 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

1XEVDO Rev A

Codec	OPUS Bitrate 6Kbps	OPUS Bitrate 40Kbps	OPUS Bitrate 75Kbps	Orientation	Band / Channel		
ABM 1 (dBA/m)	-5.99	-6	-6.07				
ABM 2 (dBA/m)	-42.39	-42.12	-40.75		DO4 / 600		
Signal Quality (dB)	36.4	36.12	34.68	Axial	BC1 / 600		
Freq. Response	Pass	Pass	Pass				

Report No.: HA922117B

Remark: According to codec investigation, the worst codec bitrate is 75kbps

LTE FDD

Codec	OPUS Bitrate 6Kbps	Bitrate Bitrate Bitrate		Orientation	Band / BW / Channel		
ABM 1 (dBA/m)	-5.34	-6.29	-6.23				
ABM 2 (dBA/m)	-38.97	-40.23	-39.35		DOE / 00M / 400000		
Signal Quality (dB)	33.63	33.94	33.12	Axial	B25 / 20M / 132322		
Freq. Response	Pass	Pass	Pass				

Remark: According to codec investigation, the worst codec bitrate is 75kbps

LTE TDD

Codec	OPUS Bitrate 6Kbps	e Bitrate Bitrate		Orientation	Band / BW / Channel
ABM 1 (dBA/m)	-5.04	-5.01	-5.63		
ABM 2 (dBA/m)	-31.73	-31.79	-32.1		B41 / 20M / 40620
Signal Quality (dB)	26.69	26.78	26.47	Axial	B41 / 20W / 40620
Freq. Response	Pass	Pass	Pass		

Remark: According to codec investigation, the worst codec bitrate is 75kbps

WLAN

Codec	OPUS Bitrate 6Kbps	itrate Bitrate Bitrate		Orientation	Band / Channel		
ABM 1 (dBA/m)	-3.98	-3.67	-4.43				
ABM 2 (dBA/m)	-38.49	-38.64	-37.41		WII AND 40 / C		
Signal Quality (dB)	34.51	34.97	32.98	Axial	WLAN2.4G / 6		
Freq. Response	Pass	Pass	Pass				

Remark: According to codec investigation, the worst codec bitrate is 75kbps

TEL: 886-3-327-3456 Page: 22 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

Plot No.	Air Interface	Mode	Channel	Battery	Probe Position	ABM1 dB (A/m)	ABM2 dB (A/m)	Signal Quality dB	T Rating	Ambient Noise dB (A/m)	Freq. Response Variation dB	Frequency Response
24	CCMOEO	EDCE 2 Ty cloto	100	Dottom (1	Axial (Z)	-6.96	-32.76	25.80	T3	-50.35	1.01	Door
21	GSM850	EDGE 2 Tx slots	189	Battery1	Transversal (Y)	-15.19	-41.03	25.84	T3	-50.25	1.01	Pass
22	CCM4000	EDOE 0 To alata	004	Dotto	Axial (Z)	-7.26	-37.60	30.34	T4	-50.33	4.00	Dana
22	GSM1900	EDGE 2 Tx slots	661	Battery1	Transversal (Y)	-13.55	-43.07	29.52	T3	-50.22	1.38	Pass
-00	MODMAN	HODA	0.400	D = 11 = = 4	Axial (Z)	-5.69	-40.49	34.80	T4	-50.36	4.07	D
23	WCDMA II	HSPA	9400	Battery1	Transversal (Y)	-14.52	-44.79	30.27	T4	-50.21	1.37	Pass
24	WCDMA IV	HSPA	1413	Dottom (1	Axial (Z)	-5.47	-40.13	34.66	T4	-50.34	1.56	Pass
24	WCDIVIA IV	пора	1413	Battery1	Transversal (Y)	-13.87	-44.56	30.69	T4	-50.27		
25	WCDMA V	HSPA	4400	Dottom (1	Axial (Z)	-5.73	-41.33	35.60	T4	-50.37	1.62	Pass
25	VVCDIVIA V	пора	4182	Battery1	Transversal (Y)	-14.44	-44.62	30.18	T4	-50.26		
20	CDMA BCO	DTAD 450 CKhan	20.4	Dotto	Axial (Z)	-6.32	-42.74	36.42	T4	-50.36	0	Pass
26	CDMA BC0	RTAP 153.6Kbps	384	Battery1	Transversal (Y)	-12.32	-43.78	31.46	T4	-50.24	2	
07	CDMA DC4	DTAD 450 CKhan	600	Dotto	Axial (Z)	-6.07	-40.75	34.68	T4	-50.34	4.44	Pass
27	CDMA BC1	RTAP 153.6Kbps	600	Battery1	Transversal (Y)	-12.24	-44.22	31.98	T4	-50.19	1.44	
28	CDMA BC10	RTAP 153.6Kbps	580	Dottom (1	Axial (Z)	-5.89	-42.12	36.23	T4	-50.35	2	Pass
20	CDIVIA BC 10	KTAP 153.6K0ps	360	Battery1	Transversal (Y)	-12.57	-43.79	31.22	T4	-50.20	2	Pass
29	LTE Band 66	20M ODEK 4 0	122222	Dottom (1	Axial (Z)	-6.23	-39.35	33.12	T4	-50.39	1.55	Pass
29	LIE Ballu 66	20M_QPSK_1_0	132322	Battery1	Transversal (Y)	-13.91	-43.52	29.61	T3	-50.28	1.55	Fa55
30	LTE Band 41	20M QPSK 1 0	40620	Batterv1	Axial (Z)	-5.63	-32.10	26.47	T3	-50.31	1 17	Door
30	LIE Band 41	20101_QP3K_1_0	40620	Бацегут	Transversal (Y)	-13.87	-43.00	29.13	T3	-50.24	1.47	Pass
31	WLAN2.4GHz	802.11b 1Mbps	6	Battery1	Axial (Z)	-4.43	-37.41	32.98	T4	-50.32	1.24	Pass
اد	VVLAINZ.4GHZ	OUZ. I ID TIVIDPS	0	Бацегут	Transversal (Y)	-16.52	-41.58	25.06	T3	-50.22		FdSS
32	MI ANECH-	902 110 6Mbss	124	Pottor:4	Axial (Z)	-4.23	-37.92	33.69	T4	-50.36	1 12	Door
32	WLAN5GHz	802.11a 6Mbps	124	Battery1	Transversal (Y)	-16 67	-41 82	25 15	T3	-50.26	1.13	Pass

Transversal (Y) -16.67 -41.82 25.15

-50.26

Report No.: HA922117B

Remark:

1. Phone Condition: Mute on; Backlight off; Max Volume

2. The detail frequency response results please refer to appendix A.

3. Test Engineer: Tom Jiang

TEL: 886-3-327-3456 Page: 23 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

12. Uncertainty Assessment

The evaluation of uncertainty by the statistical analysis of a series of observations is termed a Type A evaluation of uncertainty. The evaluation of uncertainty by means other than the statistical analysis of a series of observation is termed a Type B evaluation of uncertainty. Each component of uncertainty, however evaluated, is represented by an estimated standard deviation, termed standard uncertainty, which is determined by the positive square root of the estimated variance. The combined standard uncertainty of the measurement result represents the estimated standard deviation of the result. It is obtained by combining the individual standard uncertainties of both Type A and Type B evaluation using the usual "root-sum-squares" (RSS) methods of combining standard deviations by taking the positive square root of the estimated variances. Expanded uncertainty is a measure of uncertainty that defines an interval about the measurement result within which the measured value is confidently believed to lie. It is obtained by multiplying the combined standard uncertainty by a coverage factor. For purpose of this document, a coverage factor two is used, which corresponds to confidence interval of about 95 %. The DASY uncertainty Budget is showed in Table 8.2. The judgment of conformity in the report is based on the measurement results excluding the measurement uncertainty.

Report No.: HA922117B

Error Description	Uncertainty Error Description Value (±%)		Divisor	Ci (ABM1)	Ci (ABM2)	Standard Uncertainty (ABM1)	Standard Uncertainty (ABM2)
		Probe Sen	sitivity				
Reference Level	3.0	Normal	1	1	1	± 3.0 %	± 3.0 %
AMCC Geometry	0.4	Rectangular	√3	1	1	± 0.2 %	± 0.2 %
AMCC Current	1.0	Rectangular	√3	1	1	± 0.6 %	± 0.6 %
Probe Positioning During Calibrate	0.1	Rectangular	√3	1	1	± 0.1 %	± 0.1 %
Noise Contribution	0.7	Rectangular	√3	0.0143	1	± 0.0 %	± 0.4 %
Frequency Slope	5.9	Rectangular	√3	0.1	1	± 0.3 %	± 3.5 %
		Probe Sy	stem				
Repeatability / Drift	1.0	Rectangular	√3	1	1	± 0.6 %	± 0.6 %
Linearity / Dynamic Range	0.6	Rectangular	√3	1	1	± 0.4 %	± 0.4 %
Acoustic Noise	1.0	Rectangular	√3	0.1	1	± 0.1 %	± 0.6 %
Probe Angle	2.3	Rectangular	√3	1	1	± 1.4 %	± 1.4 %
Spectral Processing	0.9	Rectangular	√3	1	1	± 0.5 %	± 0.5 %
Integration Time	0.6	Normal	1	1	5	± 0.6 %	± 3.0 %
Field Disturbation	0.2	Rectangular	√3	1	1	± 0.1 %	± 0.1 %
		Test Siç	gnal				
Reference Signal Spectral Response	0.6	Rectangular	√3	0	1	± 0.0 %	± 0.4 %
		Position	ning				
Probe Positioning	1.9	Rectangular	√3	1	1	± 1.1 %	± 1.1 %
Phantom Thickness	0.9	Rectangular	√3	1	1	± 0.5 %	± 0.5 %
EUT Positioning	1.9	Rectangular	√3	1	1	± 1.1 %	± 1.1 %
External Contributions							
RF Interference	0.0	Rectangular	√3	1	0.3	± 0.0 %	± 0.0 %
Test Signal Variation	2.0	Rectangular	√3	1	1	± 1.2 %	± 1.2 %
	Combined Star	ndard Uncertainty				± 4.1 %	± 6.1 %
	Coverage F	actor for 95 %				K	= 2
	Expanded	Uncertainty				± 8.1 %	± 12.3 %

Table 8.2 Uncertainty Budget of audio band magnetic measurement

TEL: 886-3-327-3456 Page: 24 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019

13. References

[1] ANSI C63.19-2011, "American National Standard for Methods of Measurement of Compatibility between Wireless Communications Devices and Hearing Aids", 27 May 2011.

Report No.: HA922117B

- [2] FCC KDB 285076 D01v05, "Equipment Authorization Guidance for Hearing Aid Compatibility", Sep 2017
- [3] FCC KDB 285076 D02v03, "Guidance for performing T-Coil tests for air interfaces supporting voice over IP (e.g., LTE and WiFi) to support CMRS based telephone services", Sep 2017
- [4] FCC KDB 285076 D03v01, "Hearing aid compatibility frequently asked questions", Sep 2017
- [5] SPEAG DASY System Handbook

TEL: 886-3-327-3456 Page: 25 of 25
FAX: 886-3-328-4978 Issued Date: Apr. 24, 2019