
B. AMPS Pattern Adapter


with (4) Mounting Screws

C. Car Adapter

D. Cable Clips (2)



INCLUDED ELEMENTS



DEVICE SETUP

SECTION A - Universal AMPS Pattern Adapter

SECTION B - Integrated Cable Management System

SECTION C - Connection & Charging


SECTION **D** - Charging Head Adjustment

SECTION A

Universal AMPS Pattern Adapter Installation

Note: The Universal AMPS Pattern Adapter should be installed disassembled from the MagicMount Charge Elite.

- 1. Remove the ball collar from adapter plate and remove the MagicMount.
- 2. Position the adapter plate on the AMPS Mounting Location.
- 3. Use a Phillips Head screwdriver to attach the adapter plate with (4) self-driving screws, included.
- 4. Replace the MagicMount. Place the ball connector through the collar into the ball socket. Note: Make sure the "Scosche" side of the collar is facing outward (toward the MagicMount).
- 5. Tighten the collar onto the ball socket.










MAGICMOUNT CHARGE ELITE integrated Cable Management System

Release the cable from the output slot (A)

2. Manually unwind the cable from the internal storage reei (B), or wind the cable onto the storage reel (C) to adjust the length of exposed cable.

Minimum Length. 1 ft Maximum Length. 4 ft


3. At the desired length, replace the cable in the output slot (D)







Loosen ball-joint collar (A) to adjust charging head angle (B) or rotate device 360° (C).





Scosche Industries 1550 Pacific Avenue Oxnard, California 93033 Pnone 800-363 4490 x1 / 805-486-4450 x1

©2024 Scosche Industries

Scosche & MagicMount are trademarks of Scosche Industries.
Other marks or brands are the property of their respective owners
Devices and or appearance may vary.

Designed in Oxnard, California

SI MEQWRAMPS: 7/24