



ANNEX 1 - PLOTS OF TRANSIENT FREQUENCY BEHAVIOR MEASUREMENTS PLOT # 31
For 25 kHz Channel Spacing Operation **FCC IDL I MA-P2085A**

Transmitter's Operation: The transmitter is being turn "ON", FM modulation is off



ANNEX 1 - PLOTS OF TRANSIENT FREQUENCY BEHAVIOR MEASUREMENTS PLOT # 32
For 25 kHz Channel Spacing Operation FCC IDL I MA-P2085A


Transmitter's Operation: The transmitter is being turn "OFF", FM modulation is off



ANNEX 1 - PLOTS OF TRANSIENT FREQUENCY BEHAVIOR MEASUREMENTS PLOT # 33
For 25 kHz Channel Spacing Operation FCC ID I MA-P2085A

Transmitter's Operation: The transmitter is being turn "ON", FM Modulation with 1 kHz Sine Wave Signal

Remark: The voice modulation is delayed by 75 mS after the transmitter is turned on.



ANNEX 1 - PLOTS OF TRANSIENT FREQUENCY BEHAVIOR MEASUREMENTS PLOT # 34
For 25 kHz Channel Spacing Operation FCC IDL I MA-P2085A

Transmitter's Operation: The transmitter is being turn "OFF", FM Modulation with 1 kHz Sine Wave Signal

