


ANNEX 1 - PLOTS OF MEASUREMENTS
TRANSIENT FREQUENCY BEHAVIOR

PLOT # 34


25 kHz Channel Spacing, Transmitter was being turned ON, NO MODULATION



ANNEX 1 - PLOTS OF MEASUREMENTS
TRANSIENT FREQUENCY BEHAVIOR

PLOT # 35

25 kHz Channel Spacing, Transmitter was being turned OFF, NO MODULATION




ANNEX 1 - PLOTS OF MEASUREMENTS

TRANSIENT FREQUENCY BEHAVIOR

PLOT # 36

25 kHz Channel Spacing, Transmitter was being turned ON, FM MODULATION WITH 1 kHz Sine Wave Signal

The modulation of this transmitter is delayed by approximately 70 mS after the transmitter is turned on



ANNEX 1 - PLOTS OF MEASUREMENTS
TRANSIENT FREQUENCY BEHAVIOR

PLOT # 37

25 kHz Channel Spacing, Transmitter was being turned OFF, FM MODULATION with 1 kHz Sine Wave Signal

