
Underwriters Laboratories, Inc.
Test Report on Electromagnetic Compatibility
Test Report: 060036 Project: 06CA05511 File: MC1324 Issued: 04/27/06

Page 1 of 5


### Internal Photo – Button Side detail



### Underwriters Laboratories, Inc. Test Report on Electromagnetic Compatibility Internal Photos

Issued: 04/27/06 Page 2 of 5 IC: 3558A-HCT01


### Internal Photo - Reverse side detail



# Underwriters Laboratories, Inc. Test Report on Electromagnetic Compatibility Internal Photos

Issued: 04/27/06 Page 3 of 5 IC: 3558A-HCT01

Internal Photo - Cover open showing keypad side and battery door



# Underwriters Laboratories, Inc. Test Report on Electromagnetic Compatibility Internal Photos

Issued: 04/27/06 Page 4 of 5 IC: 3558A-HCT01

Internal Photo - Cover open showing reverse side and battery door



# Underwriters Laboratories, Inc. Test Report on Electromagnetic Compatibility Internal Photos

Issued: 04/27/06 Page 5 of 5 IC: 3558A-HCT01