

14.02.2012

### Electrical labelings of Polar RCX3 Training computer

Some of the Certification and Compliance labelings are implemented as “Electrical labelings” in RCX3 model.



RCX3 must be in the Watch-mode to be able to activate the Electrical labelings. From the Sleep-mode, the Watch-mode is activated by pressing START-button several times until all the basic settings are done and RCX3 is in the Watch-mode.

14.02.2012

From the Watch-view, press first UP-button once and DOWN-button once to go to the Settings -selections



Press then START-button once and DOWN-button three times to go to the General settings -selections



14.02.2012

Press then START-button to open the General settings view



**START**

Press then LIGHT-button until the view of the Electrical labelings appears, a long press is needed



**LIGHT**

**Currently implemented certification and compliance info:**

FCC ID INWX1  
IC: 6248A-X1

To go back to the Watch –view, press BACK-button several times until the Watch-view appears again.