

14.06.2012

### Electrical labeling in Polar RC3 GPS Training computer

Some of the Certification and Compliance information are implemented as “Electrical labeling” in the RC3 GPS training computer.

End users are guided to find electrical labeling by the user manual..



RC3 GPS must be in the Watch-mode to be able to activate the Electrical labeling. From the Sleep-mode, the Watch-mode is activated by pressing START-button several times until all the basic settings are done and RC3 GPS is in the Watch-mode.

In the Watch-view, press first UP/ DOWN buttons to the Settings menu.



Select settings by START-button then go to the General settings menu by UP/ DOWN buttons



Press then START-button to open the General settings view

14.06.2012



Press and keep the LIGHT-button pressed until the view of the Electrical labeling appears, a long press (2s) is needed.



**Currently implemented certification and compliance info is:**

USA: FCC ID INWX4  
Canada: IC: 6248A-X4  
Australia: N2965  
New Zealand: Z795

To go back to the Watch –view, press BACK-button several times until the Watch-view appears again.