

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E

Annex 3 - Internal Photographs




Photo 1. TX and RX Board Covered

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 2. Top View of TX

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 3. Top View of RX

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 4. Top Side of Main RX Board

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 5. Top Side of Main RX Board

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 6. Back Side of TX

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 7. Back Side of RX

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 8. Back Side of RX Child Board (73IFNT)

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 9. Back Side of RX VCO Board

US Tech:
Client:
Issue Date:
Model:
FCC ID:

11-0209
Kyodo West
10-06-11
KG506-40E25K
IOJKG50640E




Photo 10. Back Side of TX VCO Board