

FCC ID: IOWRMO378UP

Issued on Sep. 22, 2005

5.3.8. Photographs of Radiated Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 16 of 21


Report No.: FR590805

Issued Date : Sep. 22, 2005



FCC ID: IOWRMO378UP Issued on Sep. 22, 2005

Report No.: FR590805



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 17 of 21

Issued Date : Sep. 22, 2005