Tune-up Procedure

The 26 MHz crystal used by the Bluetooth transceiver does not have any adjustment. Transceiver functional performance is measured at the board level and final testing in production on a pass fail basis.

Rogers Labs, Inc.Garmin International, Inc.4405 West 259^{th} TerraceModels: Nuvi 3760 and Nuvi 3790GPN: 011-02353-10Louisburg, KS 66053Test #: 100215SN: 3717520185Phone/Fax: (913) 837-3214Test to: CFR47 Parts 2 and 15.249, RSS-210Revision 1File: TunPro 01652

FCC ID#: IPH-01652 IC: 1792A-01652 Page 1 of 1 Date: April 19, 2010