

Forerunner 610 Transmitter tune-up procedures

ANT is tested during unit production by measuring the output strength of a 2.457 GHz continuous wave with a nearby receiver. The unit is then given pass/fail status based on the measured output strength. The pass/fail threshold is determined by engineering during product development.