Tune-up Procedure

Each unit is tested during unit production by measuring the output strength. The unit is then given pass/fail status based on the measured output strength. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and non-compliant units are removed.

Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053

Revision 1

Garmin International, Inc. Model: A03001 Test #: 160322

Phone/Fax: (913) 837-3214 Test to: CFR47 15C, RSS-Gen RSS-210 File: A03001 TunPro

SN's: 12626, 69342 FCC ID: IPH-03001 IC: 1792A-03001 Date: June 1, 2016 Page 1 of 1