



Inside case



Transmitter portion of Board




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1


Garmin International, Inc.  
Model: A03474  
Test #: 180723  
Test to: CFR47 15C, RSS-Gen, RSS-210  
File: A03474 Short Term Conf IntPho

SN's: 3972656155, 3972656156  
FCC ID: IPH-03474  
IC: 1792A-03474  
Date: October 10, 2018  
Page 1 of 3

Front



Rear




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03474  
Test #: 180723  
Test to: CFR47 15C, RSS-Gen, RSS-210  
File: A03474 Short Term Conf IntPho

SN's: 3972656155, 3972656156  
FCC ID: IPH-03473  
IC: 1792A-03473  
Date: October 10, 2018  
Page 2 of 3

Antenna Location



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03474  
Test #: 180723  
Test to: CFR47 15C, RSS-Gen, RSS-210  
File: A03474 Short Term Conf IntPho

SN's: 3972656155, 3972656156  
FCC ID: IPH-03473  
IC: 1792A-03473  
Date: October 10, 2018  
Page 3 of 3