


PCB top side shield removed




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03654  
Test: 191024  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A03654 Short Term Conf IntPho

SN's: 3310107016, 3310107013  
FCC ID: IPH-03654  
IC: 1792A-03654  
Date: March 27, 2020  
Page 1 of 5

PCB bottom side




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03654  
Test: 191024  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A03654 Short Term Conf IntPho

SN's: 3310107016, 3310107013  
FCC ID: IPH-03654  
IC: 1792A-03654  
Date: March 27, 2020  
Page 2 of 5

Interior and 2.4 GHz Antenna



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03654  
Test: 191024  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A03654 Short Term Conf IntPho

SN's: 3310107016, 3310107013  
FCC ID: IPH-03654  
IC: 1792A-03654  
Date: March 27, 2020  
Page 3 of 5

Interior PCB installed




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03654  
Test: 191024  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A03654 Short Term Conf IntPho

SN's: 3310107016, 3310107013  
FCC ID: IPH-03654  
IC: 1792A-03654  
Date: March 27, 2020  
Page 4 of 5

NFC Antenna



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03654  
Test: 191024  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A03654 Short Term Conf IntPho

SN's: 3310107016, 3310107013  
FCC ID: IPH-03654  
IC: 1792A-03654  
Date: March 27, 2020  
Page 5 of 5