


PCB Top With shields




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03866
Test: 191202B
Test to: CFR47 15C, RSS-Gen RSS-247
File: A03866 Short Term Conf IntPho

SN's: 6B0000210, 33173 89024
FCC ID: IPH-03866
IC: 1792A-03866
Date: April 2, 2020
Page 1 of 4

PCB Top Shields removed




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03866
Test: 191202B
Test to: CFR47 15C, RSS-Gen RSS-247
File: A03866 Short Term Conf IntPho

SN's: 6B0000210, 33173 89024
FCC ID: IPH-03866
IC: 1792A-03866
Date: April 2, 2020
Page 2 of 4

PCB Bottom




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03866
Test: 191202B
Test to: CFR47 15C, RSS-Gen RSS-247
File: A03866 Short Term Conf IntPho

SN's: 6B0000210, 33173 89024
FCC ID: IPH-03866
IC: 1792A-03866
Date: April 2, 2020
Page 3 of 4

Antenna Locations



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A03866
Test: 191202B
Test to: CFR47 15C, RSS-Gen RSS-247
File: A03866 Short Term Conf IntPho

SN's: 6B0000210, 33173 89024
FCC ID: IPH-03866
IC: 1792A-03866
Date: April 2, 2020
Page 4 of 4